

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005058/KVY3M4**Date:** 04/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00044342201	
Claimant Vehicle No :	SJR8028E	Insured Vehicle No :	YL8828S	
Date of Loss:	20/05/2022	Nature of Claim:	TP	Claim No: SNM22D203656/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR8028E		Engine No:	PE30740710
Make & Model:	MAZDA 5, 2.0 SP.6EAT SUNROOF (A)		Chassis No:	JM6CW1071F0120967
Reg. Date:	19/01/2015 (Man. Year: 2014)		Odometer:	70366 km
Colour:	Metallic Grey			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,254.00	1,436.80	817.20	36.26
Miscellaneous Items	40.00	40.00	0.00	0.00
Labour	1,910.00	1,480.00	430.00	22.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,204.00	2,956.80	1,247.20	29.67
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	4,204.00	2,950.00	1,254.00	29.83
+ GST 7.00/7.00% (S\$)	294.28	206.50	87.78	29.83
Nett Amount (S\$)	4,498.28	3,156.50	1,341.78	29.83

INSPECTION

Date of Assignment:	31/05/2022	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	30/05/2022	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jul 2022)	
Parts:	N/A	MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR8028E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	430.00 F	*430.00 FL
2	1		*1 PC RERA BUMPER REINFORCEMENT	Repair	95.00 F	*- FL
3	1		*6 PCS REAR BUMPER CLIP @2/PCE	Necessary	12.00 F	*12.00 FL
4	1		*1 PC TAILGATE	Bent	650.00 F	*650.00 FL
5	1		*1 PC TAILGATE LOGO	Necessary	35.00 F	*35.00 FL
6	1		*1 PC TAILGATE EMBLEM - MAZDA 5	Necessary	30.00 F	*30.00 FL
7	1		*1 PC TAILGATE EMBLEM - ACTIV	Necessary	33.00 F	*33.00 FL
8	1		*1 PC TAILGATE INNER LOCK	Dented	140.00 F	*140.00 FL
9	1		*1 PC TAILGATE INNER RUBBER	Not Necessary	85.00 F	*- FL
10	1		*2 PCS REVERSE SENSOR @85/PCE	Shorted	170.00 F	*170.00 FL
11	1		*1 PC REAR END PANEL	Repair	230.00 F	*- FL
12	1		*1 PC REAR END PANEL INNER TOP GARNIHS	Not Necessary	48.00 F	*- FL
13	1		*1 PC REAR WINDSCREEN MOULDING	Necessary	70.00 F	*70.00 FL
Supplementary #1						
14	1		*1 PC TAILGATE LOWER OUTER PROTECTOR	Mtg Cracked	220.00 F	*220.00 FL
15	1		*1 PC REAR BUMPER INNER SQUARE CLIP	Necessary	6.00 F	*6.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,254.00	1,796.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	359.20
Total Parts (\$\$)	2,254.00	1,436.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC REAR WINDSCREEN GUM	40.00	40.00
Sub Total (\$\$)			40.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	2) TO REMOVE AND REFIX TAILGATE, TOP SPOILER, REAR WIPER ASSY, LOCK ASSY; CTU, WELD AND RENEW RR END PANEL AND RE-ALIGN TO SAME	New	800.00	550.00
3	3) TO PUTTY AND RESPRAY ON REAR PANEL, TAILGATE, TAILGATE LOWER GARNISH, REAR BUMPER, REINFORCEMENT	New	900.00	750.00
4	4) TO REMOVE AND REFIX REVERSE CAMERA, SENSOR, SMART KEY SENSOR AND RESET SYSTEM	New	50.00	50.00
5	5) TO RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,910.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >