

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005060/BEA3Q2**Date:** 29/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100378802
Claimant Vehicle No :	SKU7991C	Insured Vehicle No :	SKN7012R
Date of Loss:	29/05/2022	Nature of Claim:	TP
		Claim No:	4995680865SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU7991C	Engine No:	3ZRA416333
Make & Model:	TOYOTA WISH, 2.0 (A)	Chassis No:	JTDGJ20W505001479
Reg. Date:	02/12/2009 (Man. Year: 2009)	Odometer:	231875 km
Colour:	Blue		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,850.96	4,853.97	14,996.99	75.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,530.00	2,440.00	4,090.00	62.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,380.96	7,293.97	19,086.99	72.35
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	26,380.96	5,800.00	20,580.96	78.01
+ GST 7.00/7.00% (S\$)	1,846.67	406.00	1,440.67	78.01
Nett Amount (S\$)	28,227.63	6,206.00	22,021.63	78.01
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (11.0 x S\$120.00/day) (S\$)		1,320.00		
Nett Liability (S\$)		7,776.00		
Global Sum Settlement (S\$)		7,770.00		

INSPECTION

Date of Assignment:	30/05/2022	
Date Inspected:	30/05/2022	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	11.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Not Damaged	987.00 FL	*- FL
2	1		*FRONT FENDER INNER COWLING RH	Not Damaged	180.30 FL	*- FL
3	1		*FRONT DOOR RH	Dented	1,526.50 FL	*1,295.00 FL
4	1		*FRONT DOOR BLACK TAPE RH	Necessary	92.60 FL	*25.00 FL
5	1		*FRONT DOOR WEATHERSTRIP RH	Torn	272.00 FL	*154.90 FL
6	1		*FRONT DOOR INNER LOCK RH	Jammed	358.30 FL	*358.30 FL
7	1		*FRONT DOOR INNER LOCK STRIKER RH	Not Damaged	68.00 FL	*- FL
8	1		*FRONT DOOR FRAME RUBBER RH	Not Damaged	106.90 FL	*- FL
9	1		*FRONT DOOR TRIMBOARD RH	Broken	397.90 FL	*397.90 FL
10	1		*FRONT DOOR REGULATOR RH	Bent	332.00 FL	*158.00 FL
11	1		*FRONT DOOR REGULATOR MOTOR RH	Jammed	421.00 FL	*421.00 FL
12	1		*FRONT DOOR GLASS CHANNEL RH	Necessary	177.30 FL	*154.30 FL
13	1		*FRONT DOOR OUTER HANDLE RH	Not Damaged	210.00 FL	*- FL
14	1		*FRONT DOOR OUTER MOULDING RH	Not Damaged	104.00 FL	*- FL
15	2		*FRONT DOOR HINGE RH	Not Damaged	170.00 FL	*- FL
16	1		*FRONT DOOR CHECKER RH	Not Damaged	131.90 FL	*- FL
17	1		*SIDE MIRROR ASSY RH	Not Damaged	685.00 FL	*- FL
18	1		*DOOR CENTRE PILLAR RH	Dented	827.50 FL	*465.00 FL
19	1		*REAR DOOR RH	Dented	1,467.50 FL	*1,087.90 FL
20	1		*REAR DOOR BLACK TAPE RH	Necessary	92.60 FL	*25.00 FL
21	1		*REAR DOOR WEATHERSTRIP RH	Torn	272.00 FL	*154.00 FL
22	1		*REAR DOOR INNER LOCK RH	Not Damaged	328.90 FL	*- FL
23	1		*REAR DOOR INNER LOCK STRIKER RH	Not Damaged	86.50 FL	*- FL
24	1		*REAR DOOR TRIMBOARD RH	Not Damaged	397.90 FL	*- FL
25	1		*REAR DOOR FRAME RUBBER RH	Not Damaged	106.90 FL	*- FL
26	1		*REAR DOOR REGULATOR RH	Bent	332.00 FL	*158.00 FL
27	1		*REAR DOOR REGULATOR MOTOR RH	Not Damaged	421.00 FL	*- FL
28	1		*REAR DOOR GLASS CHANNEL RH	Not Damaged	177.30 FL	*- FL
29	1		*REAR DOOR OUTER HANDLE RH	Not Damaged	210.00 FL	*- FL
30	1		*REAR DOOR OUTER MOULDING RH	Not Damaged	104.00 FL	*- FL
31	2		*REAR DOOR HINGE RH	Bent	170.00 FL	*126.00 FL
32	1		*REAR DOOR CHECKER RH	Not Damaged	102.80 FL	*- FL
33	1		*SIDE SKIRT RH	Broken	785.30 FL	*650.00 FL
34	1		*ROCKER PANEL RH	Dented	615.00 FL	*615.00 FL
35	1		*REAR FENDER RH	Not Damaged	1,137.50 FL	*- FL
36	1		*REAR FENDER INNER TRIM BOARD RH	Not Damaged	918.00 FL	*- FL
37	1		*REAR FENDER INNER COWLING RH	Not Damaged	185.90 FL	*- FL
38	1		*REAR FENDER SIDE GLASS MOULDING RH	Not Damaged	227.60 FL	*- FL
39	1		*FRONT KNUCKLE ARM RH	Not Damaged	398.00 FL	*- FL
40	1		*FRONT KNUCKLE ARM BEARING RH	Not Damaged	245.50 FL	*- FL
41	1		*FRONT SHOCK ABSORBER RH	Not Damaged	364.00 FL	*- FL
42	1		*FRONT LOWER ARM RH	Not Damaged	535.25 FL	*- FL
43	1		*STEERING RACK	Not Damaged	1,108.00 FL	*- FL
44	1		*REAR SHOCK ABSORBER RH	Not Damaged	412.50 FL	*- FL
45	1		*REAR AXLE	Not Damaged	1,688.00 FL	*- FL
46	1		*REAR WHEEL HUB WITH BEARING RH	Not Damaged	369.80 FL	*- FL
47	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
48	1		*FRONT FENDER SEALANT	Not Damaged	100.00 FS	*- FS
49	1		*FRONT FENDER INNER COWLING CLIPS	Not Damaged	50.00 FS	*- FS
50	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
51	1		*FRONT DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
52	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
53	1		*SIDE MIRROR SEAL	Not Damaged	60.00 FS	*- FS
54	1		*DOOR CENTRE PILLAR SEALANT	Necessary	100.00 FS	*30.00 FS
55	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
57	1		*REAR DOOR TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
58	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*30.00 FS
59	1		*ROCKER PANEL SEALANT	Necessary	100.00 FS	*20.00 FS
60	1		*REAR FENDER SEALANT	Not Damaged	100.00 FS	*- FS
61	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Damaged	50.00 FS	*- FS
62	1		*REAR FENDER INNER COWLING CLIPS	Not Damaged	50.00 FS	*- FS
63	1		*REAR FENDER SIDE GLASS SEALANT	Not Damaged	100.00 FS	*- FS
64	1		*REAR FENDER SIDE GLASS INNER SEAL	Not Damaged	60.00 FS	*- FS
65	1		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Damaged	80.00 FS	*- FS
66	2		*FRONT & REAR ALLOY RIM RH	Not Damaged	1,960.00 FS	*- FS
67	2		*FRONT & REAR TYRE RH	Not Damaged	960.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,927.95	6,415.30
- List Item Discount on L Items 25.00/25.00% (\$)	5,076.99	1,561.33
Total Parts (\$)	19,850.96	4,853.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	80.00
2	R&R DOOR CENTRE PILLAR INNER GARNISH	New	100.00	30.00
3	R&R REAR DOOR COMPONENT	New	150.00	80.00
4	R&R REAR FENDER SIDE GLASS	New	250.00	0.00
5	R&R FUEL TANK PIPE	New	150.00	0.00
6	R&R REAR BUMPER REVERSE SENSOR	New	100.00	0.00
7	R&R FRONT & REAR UNDERCARRIAGE	New	600.00	0.00
8	R&R FRONT & REAR TYRE AND BALANCING	New	200.00	0.00
9	R&R STEERING RACK	New	150.00	0.00
10	WHEEL ALIGNMENT	New	180.00	0.00
11	CHECK WIRING	New	100.00	50.00
12	UPHOLSTERY	New	300.00	0.00
13	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
14	PANEL BEAT	New	1,800.00	1,200.00
15	RUST PROOFING	New	200.00	0.00
16	SPRAY PAINT	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			6,530.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >