

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005062/AYA3Q2**Date:** 24/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0001392_02
Claimant Vehicle No : SND3111G **Insured Vehicle No :** SJP4089R
 Date of Loss: 26/05/2022 Nature of Claim: TP Claim No: MPC2022D0002748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND3111G**
 Make & Model: OPEL CROSSLAND, 1.2 (A) Engine No: 10XVDU1817068
 Reg. Date: 21/12/2021 (Man. Year: 2021) Chassis No: W0V7D9EL7M4210559
 Colour: White Odometer: 4304 km
 Engine Capacity: 1199 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,485.70	3,563.40	7,922.30	68.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	480.00	3,950.00	89.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,915.70	4,043.40	11,872.30	74.59
+ GST 7.00/7.00% (S\$)	1,114.10	283.04	831.06	74.59
Nett Amount (S\$)	17,029.80	4,326.44	12,703.36	74.59
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,633.89		

INSPECTION

Date of Assignment: 30/05/2022
 Date Inspected: 01/06/2022 Inspected At: Xin Hua Workshop Pte Ltd
 8 KAKI BUKIT AVE 4 #04-07
 Singapore 415875
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 12 Dec 2022)	
Parts:	N/A	OPEL CROSSLAND 1.2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND3111G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR TAILGATE	Repair	2,155.00 FL	*- FL
2	1		*RR TAILGATE OPEL LOGO	Necessary	92.00 FL	*92.00 FL
3	1		*RR TAILGATE CROSSLAND X EMBLEM	Necessary	85.00 FL	*85.00 FL
4	1		*RR TAILGATE TURBO EMBLEM	Not Necessary	84.00 FL	*- FL
5	1		*RR TAILGATE WEATHERSTRIP	Cut	414.00 FL	*414.00 FL
6	1		*RR TAILGATE LOCK	Not Necessary	287.00 FL	*- FL
7	1		*RR TAILGATE LOCK CATCHER -STRIKER	Not Necessary	135.00 FL	*- FL
8	1		*RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Not Necessary	151.00 FL	*- FL
9	1		*RR TAILGATE STOPED	Not Necessary	35.00 FL	*- FL
10	1		*RR TAILGATE GLASS WITH MLDG	Not Necessary	945.00 FL	*- FL
11	1		*RR BUMPER CENTRE	Deformed	1,120.00 FL	*1,120.00 FL
12	1		*RR BUMPER RH	Not Necessary	631.00 FL	*- FL
13	1		*RR BUMPER LH	Not Necessary	631.00 FL	*- FL
14	1		*RR BUMPER REFLECTOR RH	Cracked	124.00 FL	*124.00 FL
15	1		*RR BUMPER REFLECTOR LH	Not Necessary	124.00 FL	*- FL
16	1		*RR BUMPER TOW COVER	Deformed	112.00 FL	*112.00 FL
17	1		*RR BUMPER SIDE RETAINER RH (INNER)	Damaged	161.00 FL	*161.00 FL
18	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Not Necessary	140.00 FL	*- FL
19	1		*RR BUMPER CENTER RETAINER	Cracked	164.00 FL	*164.00 FL
20	1		*RR BUMPER SIDE RETAINER LH (INNER)	Not Necessary	161.00 FL	*- FL
21	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Not Necessary	140.00 FL	*- FL
22	1		*RR BUMPER LOW BRACKET CENTRE RH	Cracked	95.00 FL	*95.00 FL
23	1		*RR BUMPER LOW BRACKET CENTRE LH	Not Necessary	95.00 FL	*- FL
24	1		*RR BUMPER REINFORCEMENT	Dented	703.00 FL	*703.00 FL
25	4		*RR BUMPER REVERSE SENSOR -INNER	Damaged (1 PCS ONLY)	828.00 FL	*207.00 FL
26	6		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	72.00 FL	*72.00 FL
27	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	388.00 FL	*- FL
28	1		*RR END PANEL	Repair	409.00 FL	*- FL
29	1		*RR END PANEL AIR DUCT -VENT	Cracked	126.00 FL	*126.00 FL
30	1		*RR END PANEL TOP GARNISH	Not Necessary	251.00 FL	*- FL
31	1		*RR FENDER PROTECTOR RH	Not Necessary	132.00 FL	*- FL
32	1		*RR FENDER PROTECTOR LH	Not Necessary	132.00 FL	*- FL
33	1		*REAR BUMPER COVER GARNISH	Deformed	451.00 FL	*451.00 FL
34	1		*RR NUMBER PLATE WITH CASING	Not Necessary	70.00 FS	*- FS
35	10		*RR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
36	10		*RR TAILGATE TRIM CLIP	Not Necessary	60.00 FS	*- FS
37	10		*RR END PANEL GARNISH CLIP	Not Necessary	60.00 FS	*- FS
38	1		*RR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
39	1		*RR WARNING SIGN BOARD	Not Necessary	250.00 FS	*- FS
40	1		*RR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*RR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
42	1		*RR WINDSCREEN SOLAR FILM	Not Necessary	250.00 FS	*- FS
43	1		*BODY PANEL JOINT SEALER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) 12,643.00 3,956.00**- List Item Discount on L Items 10.00/10.00% (\$)** 1,157.30 392.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	11,485.70	3,563.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	200.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA ,RR TAILGATE ,RR BUMPER ,RR END PANEL ,RR SPARE TYRE PANEL ,RR FENDER RH ,RR FENDER LH	New	1,400.00	200.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	80.00	0.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
5	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	200.00	0.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	100.00	50.00
7	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	100.00	0.00
8	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	200.00	0.00
9	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	100.00	0.00
10	TO REMOVE AND REPLACE EXHAUST PIPE	New	200.00	0.00
11	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	180.00	0.00
12	TO PERFORM DIAGNOSIS RESET ON FAULT CODE	New	350.00	0.00
Gross Labour Cost (S\$)			4,430.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >