

Auto Insure Pte. Ltd. 6 Marsiling Lane Singapore (739145) E: claims01@autoinsure.com.sg

W: www.autoinsure.com.sg T: 3157 2626 F: 6368 0081

GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: GBL2394M (MARVYN)

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

25-May-22

79 Robinson Road

#09-01.

Date:

Singapore 068897

Assessed Vehicle No

: GBL2394M

Car Make and Model

: TOYOTA HIACE DX 2.8 AUTO

Date of Accident

: 15-May-22

Date of Assessment

: 25-May-22

We have carried out a physical assessment of GBL2394M at our workshop Auto Insure Pte Ltd sustained damages to the FRONT portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

P/P

Adjusted Amount

: \$ 22,309.50

Est. Repair Days

18

Pursuant to your instruction, we have AUTHORIZED to repair.

The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: GBL2394M ASSESSED EST. BY WORKSHOP DESCRIPTIONS CONDITION QTY S/NO PARTS REPLACEMENT - LIST ITEMS 720.00 FRONT WINDSCREEN 1 1 \$ 55.00 FRONT WINDSCREEN MOULDING 1 2 /60.00 FRONT WINDSCREEN WIPER ARM RH 1 3 60.00 FRONT WINDSCREEN WIPER ARM LH 1 4 420.00 FRONT WINDSCREEN WIPER MOTOR 5 1 160.00 FRONT WINDSCREEN WIPER LINKAGE 7 1 6 20.00 FRONT WIPER COVER 1 7 / 100.00 FRONT WIPER TANK 1 8 CHECK FRONT COWL PANEL 9 1 265.00 BONNET 54/ 10 1 \$ 45.00 BONNET HINGE RH 11 1 BONNET HINGE LH \$ 45.00 12 1 \$ BONNET SUPPORT) 220.00 13 1 FRONT FENDER RH \$ 100.00 14 1 FRONT FENDER BRACKET RH 1 15 CHECK FRONT FENDER LH Suc 16 1 \$ 100.00 FRONT FENDER BRACKET LH 17 1 CHECK FRONT FENDER SIDE MIRROR ASSEMBLY LH hru 18 1 / 145.00 FRONT UPPER GRILLE CALL 19 1 \$ **160.00** 20 1 FRONT LOWER GRILLE CM \$ V280.00 FRONT GRILLE BASE CA 21 1 \$ 265.00 FRONT BUMPER del 22 1 205.00 23 FRONT BUMPER LOWER GRILLE 1 \$ **/**85.00 FRONT BUMPER LOWER COVER RH 24 1 \$ 45.00 25 1 FRONT BUMPER LOWER COVER LH \$ 45.00 26 1 FRONT BUMPER REINFORCEMENT \$ 135.00 27 FRONT PANEL CROSSMEMBER 1 CHECK FRONT LOCK CARRIER PANEL 28 1 CHECK FRONT SUPPORT PANEL 54/ 29 1 220.00 30 1 FRONT LOWER CROSSMEMBER CHECK 31 1 FRONT SUPPORT PANEL STRUT CHECK 32 1 FRONT ENGINE FIREWALL CHECK FRONT ENGINE FIREWALL INSULATION ? 33 1 CHECK 34 1 FRONT FUSE BOX TOP COVER '-CHECK 1 FRONT FUSE BOX BOTTEM COVER 35 CHECK 1 FRONT FUSE BOX RELAY BLOCK 36 CHECK 1 FRONT AIR INTAKE MANIFOLD 37 CHECK 1 FRONT INTAKE CHANNEL 38 CHECK 1 FRONT FILTER INTAKE HOSE 39 CHECK FRONT AIR FILTER ASSEMBLY . 1 40 \$ 340.00 FRONT BRAKE BOOSTER 🗡 1 41 \$ 660.00 FRONT BRAKE MASTER CYLINDER X 1 \$ 42 420.00 FRONT BRAKE FLUID TANK 43 1 W/CYLINDER FRONT A PILLAR LH 1 44 /230.00 FRONT A PILLAR INNER LH 1 1 \$ 45 265.00 FRONT A PILLAR TRIM LH 46 120.00

47	1	FRONT A PILLAR LOWER FRAME 7	ï	
48	1	KEINFORCEMENTIH		CHECK
GALAC		FRONT A PILLAR SIDE PANEL LH	\$	160.00
49	1	FRONT A PILLAR LOWER REINFORCEMENT LH?	,	<u> </u>
50	1	SIDE MEMBER LH repriv		CHECK
51	1	SIDE MEMBER RH X		• REPAIR
52	1	FRONT DOOR LH LW		REPAIR •
53	1	FRONT DOOR UPPER HINGE LH 37	\$	600.00
54	1	FRONT DOOR LOWER HINGE LH 14/	\$	45.00
55	1	FRONT DOOR INNER TRIM, LH	\$	45.00
56	1	FRONT DOOR LOCK LH at	\$	360.00
57	1	FRONT DOOR STRIKER LH	\$	230.00
58	1	FRONT DOOR GLASS LH	\$	• 75.00 , 195.00
59	1	FRONT DOOR SIDE MIRROR LH SUL	\$	420.00
60	1	FRONT STEP PANEL LH at	\$	60.00
61	1	FRONT STEP PANEL INNER LH 7	Š	110.00
62	1	FRONT STEP PANEL TRIM LH 7,	*	CHECK
63	1	FRONT WHEEL RIM LH 7	\$	• 255.00
64	1	FRONT SHOCKABSORBER LH	*	CHECK
65	1	FRONT KNUCKLE ARM LH ?	\$	255.00
66	1	FRONT TIE ROD LH ?	\$	90.00
67	1	FRONT TIE ROD END LH	\$	70.00
68	1	FRONT WHEEL HUB LH ?	\$	180.00
69	1	FRONT WHEEL HUB BEARING LH	\$	120.00
70	1	FRONT DASHBOARD	\$	580.00
71	1	FRONT DASHBOARD CENTER COVER		CHECK
72	1	FRONT DASHBOARD GLOVEBOX	\$	160.00
73	1	FRONT DASHBOARD UPPER TRIM		CHECK
74	1	FRONT DASHBOARD UPPER COVER		CHECK
75	1	FRONT DASHBOARD LOWER TRIM 4 !		CHECK
76	1	FRONT DASHBOARD LOWER SHIFT COVER ?		CHECK
77	1	FRONT DASHBOARD STEERING GEAR COVER		CHECK
78	1	FRONT DASHBOARD LOWER PANEL COVER .		CHECK
79	1	FRONT DASHBOARD SUPPORT	\$	460.00
80	1	FRONT AIRCON FAN HOUSING ASSEMBLY ?	1.0	CHECK
81	1	FRONT AIRCON COOLING COIL ASSEMBLY CA	\$	/ 2,520.00
82	1	DRIVER AIRBAG PUT	\$	1,020.00
83	1	AIRBAG CLOCK SPRING	31,000	CHECK
84	1	FRONT AIRBAG SENSOR		CHECK
85	1	FRONT AIRBAG CONTROL MODULE, ?		CHECK
			JB TOTAL \$	14,000.00
	1		RGIN 10% \$	1,400.00
		TOTAL	AMOUNT \$	15,400.00

Our Ref: GBL2394M

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY V	WORKSHOP	
1	1	FRONT BUMPER CLIPS		\$	50.00	54
2	1	FRONT BRAKE FLUID 🗶		\$	30.00	X

•

Our Ref:	GBLZ394M				
S/NO	DESCRIPTION		EST. BY WORKSHOP		
	LABOUR & PAINTWORK		Desira (CONSTRUCTION		
1	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS	\$	1200	2,800.00	
2	TO REMOVE & REFIT AIR CON CONDENSER, PIPES & VACUUM, INCLUDING RECHARGING GAS	\$	15	U 150.00	
3	SIMPLE WIRING	\$		20.00	
4	TO REPAIR & WELD FRONT CHASSIS RH & LH	\$	20	00.00	
5	SIMPLE WIRING	\$		20.00	
6	ANTI RUST COATING	\$		20.00	
7	PAINT MATERIALS PER PANEL	\$	800	1,600.00	

SUNDRIES

	200	
TOTAL BEFORE GST	\$	20,850.00
LESS EXCESS	\$	
TOTAL BEFORE GST	\$	20,850.00
7% GST	\$	1,459.50
TOTAL REPAIR COST	\$	22,309.50

5

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

**This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

***On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.

Yours Faithfully,

8

Jason Heng Claims Director

> LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item's) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

30/05/22 P1420
EXCESS:TBA
Revent
Reson Sections
print