

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22005068/EVCE2**Date:** 16/12/2022**REFERENCE**

Insured/Claimant:	HO WEI RUI, GILBERT	Policy No:	1900244032		
Date of Loss:	26/05/2022	Nature of Claim:	OD	Claim No:	0073132642SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH6911J		
Make & Model:	AUDI A3 SPORTBACK, 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZC33218
Reg. Date:	15/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8VXKA121470
Colour:	Red	Odometer:	23346 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$111,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	109,375.10	42,663.65	66,711.45	60.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	39,904.00	25,019.00	14,885.00	37.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	149,279.10	67,682.65	81,596.45	54.66
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	148,979.10	67,382.65	81,596.45	54.77
+ GST 7.00/7.00% (S\$)	10,428.54	4,716.79	5,711.75	54.77
Nett Amount (S\$)	159,407.64	72,099.44	87,308.20	54.77

INSPECTION

Date of Assignment:	30/05/2022		
Date Inspected:	30/05/2022	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	24.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	195.00 FS	*156.00 FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Bent	86.00 FS	*68.48 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Broken	179.00 FS	*143.20 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Broken	332.00 FS	*265.20 FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Broken	636.00 FS	*508.80 FS
7	1		*RADIATOR GRILLE	Broken	1,578.00 FS	*1,262.40 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Broken	210.00 FS	*168.00 FS
9	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
10	1		*CAUTION STICKER	Necessary	16.00 FS	*10.85 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Broken	420.00 FS	*336.00 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	211.00 FS	*168.80 FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Broken	136.00 FS	*108.80 FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	847.00 FS	*677.20 FS
15	2		*HORN - LH / RH	Broken	426.00 FS	*340.00 FS
16	2		*FRONT FENDER - LH / RH	Bent	1,908.00 FS	*1,526.40 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
18	2		*FRONT FENDER BRACKET - LH / RH	Bent	112.00 FS	*88.80 FS
19	16		*FRONT FENDER POP RIVET	Necessary	61.00 FS	*48.64 FS
20	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Necessary	136.00 FS	*108.48 FS
21	2		*FRONT FENDER BRACE - LH / RH	Bent	214.00 FS	*171.20 FS
22	2		*FRONT FENDER BRACKET END - LH / RH	Necessary	62.00 FS	*48.48 FS
23	2		*FRONT FENDER INSULATION - LH / RH	Not Necessary	96.00 FS	*- FS
24	2		*FRONT FENDER CLOSING ELEMENT END - LH / RH	Not Necessary	74.00 FS	*- FS
25	2		*FRONT WHEEL HOUSING LINER - LH / RH	Crushed	366.00 FS	*292.80 FS
26	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	60.00 FS	*- FS
27	1		*BONNET	Dented	3,370.00 FS	*2,696.00 FS
28	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
29	2		*BONNET HINGE - LH / RH	Bent	136.00 FS	*108.48 FS
30	1		*BONNET SIDE COVER - LH / RH	N/S Crushed	92.00 FS	*36.24 FS
31	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
32	1		*BONNET CATCH HOOK - UPPER	Bent	100.00 FS	*79.44 FS
33	2		*BONNET STRIKER - LH / RH	Bent	246.00 FS	*196.00 FS
34	1		*BONNET CATCH HOOK - LOWER	Bent	71.00 FS	*56.32 FS
35	2		*BONNET LOCK MICRO - SWITCH	Bent	455.00 FS	*364.00 FS
36	2		*BONNET LOCK COVER	Cut	8.00 FS	*6.40 FS
37	1		*BONNET BOWDEN CABLE - CENTER	Torn	64.00 FS	*50.56 FS
38	1		*BONNET RELEASE CABLE COVER	Missing	11.00 FS	*8.56 FS
39	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
40	1		*BONNET ABSORBER	Not Necessary	110.00 FS	*- FS
41	1		*BONNET SOUND ABSORBER	Not Necessary	244.00 FS	*- FS
42	1		*BONNET PLENUM CHAMBER	Cut	199.00 FS	*159.20 FS
43	2		*HEADLIGHT - LH / RH	Broken	11,758.00 FS	*9,406.40 FS
44	2		*HEADLIGHT POWER MODULE - LH / RH	Not Necessary	1,700.00 FS	*- FS
45	2		*HEADLIGHT CONTROL UNIT	Not Necessary	1,249.00 FS	*- FS
46	2		*LED HEAT SINK - LH / RH	Not Necessary	1,636.00 FS	*- FS
47	2		*HEADLIGHT HOSE - LH / RH	Missing	92.00 FS	*73.60 FS
48	1		*LIFT CYLINDER - LH / RH	N/S Missing	312.00 FS	*124.40 FS
49	1		*LIFT CYLINDER HOSE	Torn	78.00 FS	*62.24 FS
50	1		*LIFT CYLINDER PUMP	Broken	171.00 FS	*136.80 FS
51	1		*WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	137.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*WASH WATER RESERVOIR	Crushed	225.00 FS	*180.00 FS
53	1		*WINDSCREEN STRAINER	Missing	24.00 FS	*18.96 FS
54	1		*WINDSCREEN STRIKER END CAP	Not Necessary	24.00 FS	*- FS
55	2		*WINDSCREEN SPRAY NOZZLE HEATED - LH / RH	Not Necessary	234.00 FS	*- FS
56	1		*LOCK CARRIER	Broken	806.00 FS	*644.80 FS
57	1		*A/C CONDENSER	Dented	569.00 FS	*454.80 FS
58	1		*REFRIGERANT LINE	Bent	621.00 FS	*496.80 FS
59	1		*REFRIGERANT LINE	Bent	499.00 FS	*399.20 FS
60	1		*REFRIGERANT LINE	Bent	569.00 FS	*455.20 FS
61	1		*REFRIGERANT LINE BRACKET	Not Necessary	29.00 FS	*- FS
62	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
63	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	64.00 FS	*- FS
64	1		*ADDITIONAL RADIATOR	Dented	959.00 FS	*766.80 FS
65	2		*RADIATOR BRACKET - UPPER	Broken	90.00 FS	*71.68 FS
66	2		*RADIATOR BUSH - LOWER	Necessary	22.00 FS	*16.96 FS
67	1		*RADIATOR	Dented	1,061.00 FS	*848.80 FS
68	1		*RADIATOR FAN RING	Broken	1,488.00 FS	*1,190.40 FS
69	2		*RADIATOR AIR GUIDE - LH / RH	Broken	56.00 FS	*44.32 FS
70	1		*RADIATOR SEAL - RH OUTER	Broken	9.00 FS	*7.12 FS
71	1		*RADIATOR AIR GUIDE - UPPER CENTER	Broken	14.00 FS	*10.88 FS
72	6		*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
73	1		*QUICK RELEASE COUPLING COOLANT HOSE - FRONT	Cut	251.00 FS	*200.80 FS
74	1		*QUICK RELEASE COUPLING COOLANT HOSE - UPPER	Not Necessary	125.00 FS	*- FS
75	1		*COOLANT PIPE - UPPER	Not Necessary	65.00 FS	*- FS
76	1		*COOLANT PIPE - LOWER	Cut	34.00 FS	*26.80 FS
77	1		*QUICK RELEASE COUPLING COOLANT HOSE - LOWER	Not Necessary	60.00 FS	*- FS
78	1		*QUICK RELEASE COUPLING COOLANT HOSE	Not Necessary	159.00 FS	*- FS
79	1		*INTAKE AIR DUCT COVER	Cut	30.00 FS	*23.76 FS
80	1		*INTAKE AIR GUIDE - LOWER	Broken	59.00 FS	*46.48 FS
81	1		*INTAKE AIR GUIDE - UPPER	Crushed	21.00 FS	*16.16 FS
82	1		*WATER DRAINAGE HOSE	Not Necessary	37.00 FS	*- FS
83	1		*INTAKE AIR GUIDE - LOWER	Broken	69.00 FS	*54.64 FS
84	1		*AIR FILTER BOX	Not Necessary	310.00 FS	*- FS
85	1		*INTAKE MANIFOLD - UPPER	Not Necessary	156.00 FS	*- FS
86	1		*INTAKE MANIFOLD - LOWER	Broken	786.00 FS	*628.80 FS
87	1		*THROTTLE BODY	Not Necessary	796.00 FS	*- FS
88	1		*CHARGE AIR COOLER	Bent	864.00 FS	*691.20 FS
89	2		*TOOTHED BELT GUARD - UPPER / LOWER	Not Necessary	160.00 FS	*- FS
90	1		*TOOTHED BELT GUARD	Not Necessary	202.00 FS	*- FS
91	1		*POLY V-BELT	Not Necessary	52.00 FS	*- FS
92	1		*BATTERY CONSOLE	Broken	203.00 FS	*162.00 FS
93	1		*BATTERY HEAT INSULATION	Not Necessary	96.00 FS	*- FS
94	1		*BATTERY FILLED CHARGED	Not Necessary	584.00 FS	*- FS
95	1		*BATTERY PROTECTION COVER	Not Necessary	145.00 FS	*- FS
96	1		*BATTERY MONITORING CONTROL UNIT	Not Necessary	568.00 FS	*- FS
97	2		*FRONT FENDER TOP SUPPORT - LH / RH	Not Necessary	164.00 FS	*- FS
98	1		*FRONT CHASSIS FRAME COVER PLATE - LH	Bent	107.00 FS	*85.20 FS
99	1		*SIDE MEMBER - LH	Not Necessary	742.00 FS	*- FS
100	1		*GEARBOX MOUNTING BRACKET - LH	Not Necessary	123.00 FS	*- FS
101	1		*NOISE INSULATION	Broken	376.00 FS	*300.80 FS
102	1		*BASE ENGINE	Not Necessary	18,936.00 FS	*- FS
103	1		*SUSPENSION SUBFRAME ASSEMBLY CARRIER	Not Necessary	1,105.00 FS	*- FS
104	1		*BONDED RUBBER BUSHES	Not Necessary	116.00 FS	*- FS
105	1		*GEARBOX MOUNTING - LH	Torn	286.00 FS	*228.40 FS
106	1		*ENGINE MOUNTING - RH	Crushed	277.00 FS	*196.80 FS
107	1		*ENGINE MOUNTING CONSOLE - LH	Not Necessary	209.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*ENGINE SUPPORT	Not Necessary	243.00 FS	*- FS
109	2		*ENGINE SUPPORT - LH / RH SUPPORT	Not Necessary	50.00 FS	*- FS
110	1		*PENDULUM SUPPORT	Not Necessary	100.00 FS	*- FS
111	1		*FRONT WINDSCREEN COLOUR STRIP	Broken	1,206.00 FS	*964.80 FS
112	1		*RAIN SENSOR GEL FOIL	Necessary	130.00 FS	*104.00 FS
113	1		*SPRING CLIP	Not Necessary	23.00 FS	*- FS
114	1		*PRIMER	Necessary	22.00 FS	*17.36 FS
115	1		*WINDSCREEN WATER DEFLECTOR STRIP - LH / RH	N/S Cut	150.00 FS	*60.00 FS
116	2		*AERO WIPER ARM - LH / RH	Not Necessary	230.00 FS	*- FS
117	1		*AERODYNAMIC WIPER BLADE	Not Necessary	101.00 FS	*- FS
118	2		*AERODYNAMIC WIPER BLADE CAP	Not Necessary	20.00 FS	*- FS
119	2		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH	Not Necessary	604.00 FS	*- FS
120	2		*ROOF CHROME MOLDING - LH / RH	Not Necessary	1,330.00 FS	*- FS
121	1		*GEARBOX	Not Necessary	18,564.00 FS	*- FS
122	1		*TRANSMISSION FLUID (5PCS)	Necessary	353.00 FS	*112.96 FS
123	1		*ELECTRIC SYSTEM HOUSING	Not Necessary	93.00 FS	*- FS
124	1		*FUZE BOX COVER	Not Necessary	54.00 FS	*- FS
125	1		*ENGINE COMPARTMENT	Not Necessary	27.00 FS	*- FS
126	1		*E BOX	Not Necessary	394.00 FS	*- FS
127	1		*FRONT NO PLATE	Missing	60.00 FS	*60.00 FS
128	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
129	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
130	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
131	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
132	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
133	1		*SUNDRIES	Necessary	800.00 FS	*260.88 FS
134	1		*COVER PLATE FOR SLIDE MEMBER-LH (Supplementary)	Bent	860.00 FS	*689.20 FS
135	1		*VACUUM HOSE WITH NON-RETURN VALVE (Supplementary)	Bent	378.00 FS	*302.80 FS
136	1		*OIL FILTER (Supplementary)	Dented	28.00 FS	*22.32 FS
137	1		*MECHATRONICA WITH SOFTWARE (Supplementary)	Dented	4,426.00 FS	*3,540.80 FS
138	1		*SOCKET HEAD BOLT (4 pcs) (Supplementary)	Necessary	49.00 FS	*38.72 FS
139	1		*FLAT CONNECTOR HOUSING (Supplementary)	Broken	23.00 FS	*18.32 FS
140	1		*SET SIGNLE WIRE (2 pcs) (Supplementary)	Torn	79.00 FS	*62.88 FS
141	1		*COOLANT PUMP (Supplementary)	Broken	373.00 FS	*298.00 FS
142	1		*OIL SEPARATOR COVER (Supplementary)	Broken	16.00 FS	*12.72 FS
143	1		*OIL SEPARATOR (Supplementary)	Bent	118.00 FS	*94.40 FS
144	1		*A/C COMPRESSOR (Supplementary)	Not Necessary	2,335.00 FS	*- FS
145	1		*OIL FILTER (Supplementary)	Dented	27.90 FS	*22.32 FS
146	2		*BRAKE FLUID (Supplementary)	Necessary	69.20 FS	*55.36 FS
147	2		*SEATBELT ADJUSTER (Supplementary)	Jammed	430.00 FS	*344.00 FS
148	1		*SEAT BELT-LH (Supplementary)	Jammed	1,227.00 FS	*981.60 FS
149	1		*SEAT BELT-RH (Supplementary)	Jammed	1,227.00 FS	*981.60 FS
150	1		*AIRBAG CONTROL UNIT (Supplementary)	Necessary	1,982.00 FS	*1,585.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
151	1		*FUSE (Supplementary)	Necessary	48.10 FS	*38.48 FS
152	1		*OIL SEPERATOR (Supplementary)	Dented	290.50 FS	*232.40 FS
153	1		*ENGINE COVER SEALANT (Supplementary)	Necessary	63.40 FS	*50.72 FS
154	2		*ENGINE OIL (Supplementary)	Necessary	598.00 FS	*478.40 FS
155	1		*COOLANT HOSE (Supplementary)	Cut	139.00 FS	*111.20 FS
Total Parts (\$\$)					109,375.10	42,663.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	800.00
5	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR	New	560.00	280.00
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES	New	2,800.00	2,800.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGED AND RENEW IF NECESSARY	New	2,400.00	2,400.00
8	TO SETUP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
9	TO REMOVE AND RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS	New	980.00	980.00
10	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	0.00
12	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
13	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND LHS FRONT CHASSIS FRAME WITH COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	14,000.00	5,250.00
14	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT FENDER TOP SUPPORTS, LHS FRONT CHASSIS FRAME WITH COVER PLATE, BOTH FRONT DOORS AND BOTH UPP A-PILLARS	New	8,500.00	3,575.00
15	TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	480.00	480.00
16	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
18	TO RENEW GEARBOX MECHATRONICS AND CARRY OUT ADAPTATION (Supplementary)	New	980.00	980.00
19	TO REMOVE AND RENEW BOTH FRONT SEAT BELTS, AIRBAG CONTROL UNIT. (INCLUDE REMOVE AND REINSTALL CONSOLE) (Supplementary)	New	1,800.00	1,800.00
Gross Labour Cost (\$\$)			39,904.00	25,019.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >