

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22005094/KVY3E2

Date: 09/06/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29151485AT2
Claimant Vehicle No : SLA1760K Insured Vehicle No : SMA8770Z
Date of Loss: 28/05/2022 Nature of Claim: TP Claim No: 641590

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA1760K**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR529719
Reg. Date: 24/02/2016 (Man. Year: 2015) Chassis No: MR053REH104538382
Colour: Metallic Black Odometer: 227208 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,359.50	3,436.95	1,922.55	35.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,720.00	1,260.00	42.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,339.50	5,156.95	3,182.55	38.16
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	8,339.50	4,100.00	4,239.50	50.84

INSPECTION

Date of Assignment: 30/05/2022
Date Inspected: 31/05/2022 Inspected At: Ja Autocare Pte Ltd - Sin Ming (HQ)
160 SIN MING DRIVE, #08-16 SIN MING AUTO CITY
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA1760K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,250.00 FL	*1,079.60 FL
2	1		*FRONT LH DOOR HANDLE	Jammed	258.00 FL	*155.20 FL
3	1		*FRONT LH DOOR WEATHERSTRIP	Serviceable	110.00 FL	*- FL
4	1		*FRONT DOOR REGULATOR & MOTOR ASSY	Distorted / Jammed	560.00 FL	*560.00 FL
5	1		*FRONT LH DOOR LOCK ASSY	Dented	350.00 FL	*350.00 FL
6	1		*REAR LH DOOR	Bent	1,350.00 FL	*1,069.20 FL
7	1		*REAR LH DOOR WEATHERSTRIP	Serviceable	258.00 FL	*- FL
8	1		*REAR LH DOOR REGULATOR ASSY (WITH MOTOR)	Distorted	560.00 FL	*485.10 FL
9	1		*REAR LH DOOR LOCK ASSY	Distorted / Dented	350.00 FL	*350.00 FL
10	1		*REAR FENDER LH	Repair	850.00 FL	*- FL
11	1		*FRONT LH DOOR HANDLE INNER BRACKET LH	Cracked	250.00 FL	*125.00 FL
12	1		*FRONT LH DOOR OUTER GARNISH	Necessary	180.00 FL	*67.50 FL
13	1		*FRONT LH DOOR GLASS CHANNEL	Bent	350.00 FL	*124.90 FL
14	1		*REAR LH DOOR CHECKER	Distorted	290.00 FL	*148.60 FL
15	1		*REAR LH DOOR GARNISH	Necessary	180.00 FL	*67.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,146.00	4,582.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,786.50	1,145.65
Total Parts (S\$)	5,359.50	3,436.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DOOR BOARD, UPHOLSTERY ETC	New	220.00	80.00
2	TO TRANSFER 2 DOOR GLASS	New	240.00	120.00
3	TO CHECK WIRING	New	120.00	20.00
4	TO KNOCK OUT DENTS ON AFFECTED AREAS AND RENEW PARTS	New	1,000.00	700.00
5	TO PUTTY & RESPRAY PAINTING	New	1,400.00	800.00
			Gross Labour Cost (\$)	2,980.00
				1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >