

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIS22005097/TVY3E2
Date: 03/08/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SND9191K	Insured Vehicle No :	SNB2005Y
Date of Loss:	19/05/2022	Nature of Claim:	TP
		Claim No:	2022 22004942FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND9191K	Engine No:	L53900444
Make & Model:	LAMBORGHINI AVENTADOR LP700-4, 6.5 (A)	Chassis No:	ZHWEC147XCLA00143
Reg. Date:	21/11/2011 (Man. Year: 2011)	Odometer:	17356 km
Colour:	Pink		
Engine Capacity:	6498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/30 R20	Rear Tyre Size:	355/25 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	222,496.97	134,513.30	87,983.67	39.54	
Miscellaneous Items	0.00	0.00	0.00		
Labour	8,410.00	6,910.00	1,500.00	17.84	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	230,906.97	141,423.30	89,483.67	38.75	
Approved Total (Overridden) (S\$)		113,100.00			
	(S\$)	230,906.97	113,100.00	117,806.97	51.02
	+ GST 8.00/8.00% (S\$)	18,472.56	9,048.00	9,424.56	51.02
	Nett Amount (S\$)	249,379.53	122,148.00	127,231.53	51.02

INSPECTION

Date of Assignment:	30/05/2022		
Date Inspected:	31/05/2022	Inspected At:	Garage 13 Pte Ltd (HQ) 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46 Singapore 415875
Estimated Period of Repair:	14.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2023)
Parts: M1-COUPE	LAMBORGHINI AVENTADOR LP700-4 6.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SND9191K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	27,169.00 FL	*24,450.00 FL
2	1		*REAR BUMPER GRILLE	N/S Distorted / O/S Refix	5,878.00 FL	*2,939.00 FL
3	1		*REAR BUMPER GRILLE TRIM	N/S Broken / O/S Refix	2,640.00 FL	*1,320.00 FL
4	1		*REAR BUMPER GRILLE CENTRE	Bent	4,835.00 FL	*4,835.00 FL
5	1		*REAR BUMPER CENTER GRILLE TOP GARNISH	Cut / Cracked	1,584.00 FL	*1,584.00 FL
6	1		*REAR BUMPER LETTERING (LAMBORGHINI)	Necessary	476.00 FL	*476.00 FL
7	1		*REAR BUMPER SPOILER	Crushed	16,845.00 FL	*12,000.00 FL
8	1		*REAR BUMPER CARRIER (SUPPORT PANEL)	Bent	667.00 FL	*667.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	14,190.00 FL	*8,600.00 FL
10	1		*REAR BUMPER ARM LH	Bent	1,328.00 FL	*1,328.00 FL
11	1		*REAR BUMPER BRACKET LH	Bent	112.00 FL	*112.00 FL
12	1		*UNDERBODY TRIM CENTER	Torn	617.00 FL	*617.00 FL
13	1		*UNDERBODY TRIM SIDE RH	Not Necessary	8,032.00 FL	*- FL
14	1		*UNDERBODY TRIM SIDE LH	Torn	8,017.00 FL	*5,250.00 FL
15	1		*CENTER BRAKE LIGHT	Cracked	2,813.00 FL	*1,800.00 FL
16	2		*TAIL LAMP	Grazed / Fractured	17,388.00 FL	*12,000.00 FL
17	1		*REAR FENDER LH	Torn	12,812.00 FL	*8,000.00 FL
18	1		*REAR FENDER OUTER SUPPORT LH	Bent	98.00 FL	*98.00 FL
19	1		*REAR FENDER INNER SUPPORT LH	Bent	98.00 FL	*98.00 FL
20	1		*REAR WHEEL HOUSE LINER LH (FRONT)	Torn	2,607.00 FL	*2,607.00 FL
21	1		*REAR WHEEL HOUSE LINER LH (REAR)	Torn	1,220.00 FL	*1,220.00 FL
22	1		*SIDE SKIRT LH	Not Necessary	4,930.00 FL	*- FL
23	1		*OIL CONTAINER	Not Necessary	4,402.00 FL	*- FL
24	1		*OIL COOLER LH	Ruptered	4,735.00 FL	*3,050.00 FL
25	1		*OIL COOLER AIR DUCT (FRONT)	Torn	1,080.50 FL	*972.00 FL
26	1		*OIL COOLER AIR GUIDE (REAR)	Torn	824.00 FL	*741.00 FL
27	1		*OIL COOLER BRACKET LOWER	Bent	91.00 FL	*91.00 FL
28	1		*OIL COOLER BRACKET SIDE RH	Bent	366.00 FL	*366.00 FL
29	1		*OIL COOLER BRACKET SIDE LH	Bent	186.00 FL	*186.00 FL
30	1		*OIL PRESSURE PIPE INNER	Not Necessary	1,055.00 FL	*- FL
31	1		*OIL PRESSURE PIPE OUTER	Not Necessary	2,340.00 FL	*- FL
32	1		*AIR DUCT LH	Torn	684.00 FL	*684.00 FL
33	1		*RADIATOR	Not Necessary	4,890.00 FL	*- FL
34	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,827.00 FL	*- FL
35	1		*REAR EXHAUST SILENCER	Bent	46,572.80 FL	*30,500.00 FL
36	1		*REAR EXHAUST HEAT SHIELD (FRONT)	Deformed	1,651.00 FL	*1,450.00 FL
37	1		*REAR EXHAUST HEAT SHIELD (REAR)	Not Necessary	1,140.00 FL	*- FL
38	1		*REAR EXHAUST O RING	Necessary	175.00 FL	*175.00 FL
39	1		*REAR RIM LH	Dented	7,277.00 FL	*5,125.00 FL
40	1		*REAR TYRE LH	Abraded	5,182.00 FL	*3,000.00 FL
41	1		*REAR UPPER ARM (WISHBONE) LH	Bent	1,862.00 FL	*1,675.00 FL
42	1		*REAR LOWER ARM LH	Bent	2,640.00 FL	*2,376.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR PUSH ROD (VERTICAL) LH	Bent	1,074.00 FL	*628.00 FL
44	1		*REAR TIE ROD (HORIZONTAL) LH	Bent	370.00 FL	*370.00 FL
45	1		*REAR KNUCKLE ARM LH	Warped	1,818.00 FL	*1,818.00 FL
46	1		*REAR BRAKE CALIPER LH	Not Necessary	3,938.00 FL	*- FL
47	1		*REAR WHEEL HUB LH	Warped	3,504.00 FL	*1,000.00 FL
48	1		*REAR WHEEL HUB BEARING LH	Necessary	611.00 FL	*372.00 FL
49	1		*REAR SHOCK ABSORBER LH	Not Necessary	6,355.00 FL	*- FL
50	1		*DRIVE SHAFT LH	Bent	4,457.00 FL	*4,457.00 FL
51	1		*SET REAR BUMPER NUTS AND CLIPS	Necessary	200.00 FS	*100.00 FS
52	1		*COOLANT	Necessary	180.00 FS	*120.00 FS
53	1		*UNDERCOVER NUTS AND CLIPS	Necessary	200.00 FS	*100.00 FS
54	1		*SET REAR WHEEL HOUSE LINER CLIP LH	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	247,143.30	149,417.00
- List Item Discount on L Items 10.00/10.00% (\$)	24,646.33	14,903.70
Total Parts (\$)	222,496.97	134,513.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	3,600.00	3,000.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL AND STICKER WRAP	New	3,200.00	2,800.00
3	REMOVE AND REPLACE REAR UNDERCARRIAGE WORK LH (SPECIAL HOIST)	New	500.00	350.00
4	REMOVE / REPLACE OIL COOLER	New	480.00	300.00
5	SPECIALIST CHARGES - WHEEL ALIGNMENT	New	120.00	120.00
6	REMOVE AND REPLACE REAR EXHAUST PIPE	New	450.00	300.00
7	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	60.00	40.00
Gross Labour Cost (\$\$)			8,410.00	6,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >