# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Liu Chun Cheong Date: 02 Jun 2022

## **Preliminary Advice**

Vehicle No : SKQ8259Z Accident Date : 27/05/2022

Make : MAZDA 6 Policy No. : MPC21B00027000

Assignment Date : 30/05/2022 Excess : \$\\$0.00 Date of Inspection : 1/6/2022 Est. Duration of Repair : 5

Inspection At : JACK CARS ENTERPRISE PTE LTD

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 10,514.50 |
|-----------------------------|------|-----------|
| Revised Amount              | :S\$ | 6,089.50  |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 6,089.50  |

Lump Sum Repair :S\$

#### **Total Loss Consideration**

| New for Old Value | ·S\$ |
|-------------------|------|
| New lot Old Value | .Οψ  |

 Pre-Accident Value
 :S\$
 39,000.00

 COE / PARF Rebate
 :S\$
 23,404.00

Salvage Value :S\$

Margin for Repair :S\$ 15,596.00

#### Remarks

| ( X ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let |
|-------|---|
|       | us have your authorisation.   |

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .