

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22005098/AVY3E2**Date:** 22/12/2022**REFERENCE**

Insured/Claimant:	LOH MEE FOE EDMUND	Policy No:	MPC21B00027000	
Date of Loss:	27/05/2022	Nature of Claim:	OD	Claim No: DMPC2200218H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ8259Z		
Make & Model:	MAZDA 6, 2.0 (A)	Engine No:	PE20579363
Reg. Date:	29/12/2014 (Man. Year: 2014)	Chassis No:	JM6GJ1071F0147292
Colour:	Black	Odometer:	143828 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$39,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,303.00	6,110.50	2,192.50	26.41
Miscellaneous Items	200.00	110.00	90.00	45.00
Labour	4,600.00	1,380.00	3,220.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,103.00	7,600.50	5,502.50	41.99
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	13,103.00	6,050.00	7,053.00	53.83
+ GST 7.00/7.00% (S\$)	917.22	423.50	493.72	53.83
Nett Amount (S\$)	14,020.22	6,473.50	7,546.72	53.83

INSPECTION

Date of Assignment:	30/05/2022	Present Location:	Jack Cars Enterprise Pte Ltd (HQ)
Date Inspected:	01/06/2022	Inspected At:	Jack Cars Enterprise Pte Ltd (HQ) Blk 3007 Ubi Road 1 #01-450 Singapore 408700
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ8259Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Distorted	800.00 F	*800.00 F
2	1		*FRONT BUMPER BRACKETS (LEFT & RIGHT) (WCP)	N/s Damaged	100.00 F	*50.00 F
3	1		*FRONT BUMPER GRILLE (WCP)	Cracked	500.00 F	*500.00 F
4	1		*HEADLIGHT - LEFT (WCP)	Cracked	1,000.00 F	*1,000.00 F
5	1		*HEADLIGHT - RIGHT (WCP)	Not Necessary	1,000.00 F	*- F
6	1		*HEADLIGHT BRACKETS (LEFT & RIGHT) (WCP)	N/s Damaged	100.00 F	*50.00 F
7	1		*FRONT BUMPER LOWER LIPS (WCP)	Deformed	300.00 F	*300.00 F
8	1		*MUDGUARD - LEFT (WCP)	Missing	230.00 F	*180.00 F
9	1		*FENDER - FRONT LEFT (WCP)	Buckled	1,200.00 F	*780.00 F
Supplementary #1						
10	1		*FRONT GRILLE CHROME GARNISH - LEFT (WCP)	Cut	95.00 F	*95.00 F
11	1		*FRONT GRILLE CHROME GARNISH - RIGHT (WCP)	Not Necessary	95.00 F	*- F
12	1		*CONTROL UNIT (WCP)	Damaged	1,800.00 F	*1,800.00 F

F=Franchise part.

Sub Total (\$)	7,220.00	5,555.00
+ Margin on L,N Items 15.00/10.00% (\$)	1,083.00	555.50
Total Parts (\$)	8,303.00	6,110.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	CLIPS , SCREWS & RIVETS Necessary	100.00	50.00
2	1	NUMBER PLATE - FRONT Bent	45.00	30.00
3	1	NUMBER PLATER COVER Deformed	55.00	30.00
Sub Total (S\$)			200.00	110.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	500.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	New	2,300.00	700.00
3	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	New	500.00	30.00
Supplementary #1				
Labour Items				
4	PROGRAMMING OF ECU	New	300.00	150.00
Gross Labour Cost (S\$)			4,600.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >