



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 6482L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH SIDE MIRROR	CRACKED	1,100.00	972.00
1	RH SIDE MIRROR GLASS	MISSING	210.00	210.00
1	RH SIDE MIRROR COVER	MISSING	190.00	165.00
1	RH SIDE MIRROR SIGNAL LAMP	SCRATCHED	190.00	190.00
	LESS 10% DISCOUNT		-	-153.70
			1,690.00	1,383.30
	<u>LABOUR</u>			
	REMOVE & FIX BACK RH SIDE MIRROR.		250.00	80.00
	SPRAY FRT RH DOOR, FRT RH FENDER, BONNET. (PEARL RED)		900.00	600.00
	TOWING FEE.		120.00	50.00
			1,270.00	730.00
	GRAND TOTAL		2,960.00	2,113.30
RECOMMENDED COST OF REPAIRS				2,113.30

Report Ref No. CS/GAI22005106/Kty3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.