



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 8075A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	WHEEL RIM FRONT	DENTED / GRAZED	335.00	280.00
2	WHEEL BEARING FRONT @\$40.00	WARPED	80.00	40.00
1	WHEEL SHAFT	BENT	39.00	25.00
1	NUT WHEEL SHAFT	DENTED / GRAZED	6.00	6.00
1	DISC BRAKE FRONT	SERVICEABLE	88.00	-
1	MUDGUARD FRONT	BROKEN	84.00	68.00
1	BRAKE CALIPER FRONT	DENTED / GRAZED	295.00	212.00
1	LEVER BRAKE	BROKEN	32.00	18.00
1	BRAKE CYLINDER FRONT	SERVICEABLE	220.00	-
2	FORK FRONT LH / RH	GRAZED / BENT / JAMMED	293.00	293.00
1	UNDER BRACKET COMP	TO REPAIR SEE LABOUR	253.00	-
1	CONE BEARING	WARPED	130.00	65.00
1	COWLING FRONT	GRAZED / CUT	78.00	78.00
1	HEADLIGHT	SERVICEABLE	164.00	-
1	METER ASSY	GRAZED / CUT	511.00	390.00
2	HANDLEBAR LH / RH @\$97.00	O/S BROKEN	194.00	85.00
2	BAREND WEIGHT @\$33.00	DENTED (1PC ONLY)	66.00	25.00
1	SWITCH RH	BUTTON CRACKED	189.00	189.00
1	FUEL TANK	DENTED	590.00	390.00
1	LEVER CLUTCH	BROKEN	32.00	18.00
1	MIRROR RH	GRAZED	26.00	26.00
1	PEDAL KICK	DENTED / GRAZED	72.00	72.00
1	FOOTREST FRONT RH	DENTED	39.00	39.00
1	FOOTREST REAR RH	DENTED	32.00	32.00
1	FOOTREST SUPPORT RH	BROKEN	255.00	85.00
1	PEDAL BRAKE	DENTED	43.00	43.00
1	EXHAUST PIPE	DENTED	670.00	325.00
1	UNDER COWLING	SERVICEABLE	70.00	-
1	COWLING REAR RH	BROKEN	121.00	121.00

Report Ref No. CS3/ASM20014647/Gqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SHOCK RH	SERVICEABLE	198.00	-
1	FOOTREST FRONT LH	SERVICEABLE	39.00	-
1	FOOTREST REAR LH	SERVICEABLE	32.00	-
	LESS 10% DISCOUNT		-527.60	-292.50
			4,748.40	2,632.50
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (SN)	SERVICEABLE	150.00	-
1	HANDLE GRIP (SN)	SERVICEABLE	40.00	-
1	BRAKE FLUID (SN)	SERVICEABLE	20.00	-
1	FRONT NUMBER PLATE (SN)	GRAZED	20.00	10.00
			230.00	10.00
	<u>LABOUR</u>			
	CHECK LIGHTINGS & WIRINGS.	NOT NECESSARY	30.00	-
	RENEW & CONDUCT FORK ALIGNMENT.	NOT NECESSARY	180.00	-
	REPAIR, STRAIGHTEN & REFURBISH BODY FRAME.	NOT NECESSARY	400.00	-
	RENEW DAMAGED PARTS, RE-ALIGN AFFECTED AREA. INCLUSIVE OF THE REPAIR OF UNDER BRACKET COMP.		500.00	250.00
	TOWING FEE.		65.00	50.00
			1,175.00	300.00
	GRAND TOTAL		6,153.40	2,942.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS3/ASM20014647/Gqy3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.