

J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

VEHICLE INSPECTION REPORT

To: FRESH CARS PTE LTD

Date : 17 January 2022

C/o: A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Our ref : ATEC/01/0003/JM

Accident Date : 12 December 2021
Inspection Date : 16 December 2021
Repairer Name : A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Type of Survey : Third party

PARTICULARS OF VEHICLE

Registration No : SMW 7583 M
Make / Model : Toyota / Prius Plus
Chassis No : JTDZS3EU90J060593
Engine No : 2ZR2H38923

Year / Capacity : 2020 / 1798 cc
Colour : Silver
Mileage : 116,393 km

CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside	: Arivo	205/60/ R16	80%
Front Offside	: Arivo	205/60/ R16	80%
Rear Nearside	: Arivo	205/60/ R16	80%
Rear Offside	: Arivo	205/60/ R16	80%

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front bumper
(Details refer to the photographs attached)

Enclosed number of photographs: 40 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

Vehicle Registration No: SMW 7583 M

Our Ref No: ATEC/01/0003/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bumper assy (1 set)	Warped/Cracked	\$ 1,300.00	\$ 1,300.00	570
1	Front bumper absorber foam	Cracked	\$ 485.00	\$ 485.00	235
1	Front bumper lower grille	Warped	\$ 490.00	\$ 490.00	X NN
1	Front bumper upper grille	Reuse	\$ 520.00	\$ -	
1	Front support panel top garnish	Warped	\$ 460.00	\$ 460.00	X NN
1	Front headlamp LH RH	Cracked	\$ 1,450.00	\$ 1,450.00	X H
1	Front fog lamp LH RH	Cracked	\$ 550.00	\$ 550.00	X NN
1	Front fog lamp cover LH RH	Warped	\$ 380.00	\$ 380.00	X NN
1	Front signal lamp LH Day Running Lamp RH	Cracked	\$ 560.00	\$ 560.00	X X
1	Front signal lamp bracket LH	Warped	\$ 435.00	\$ 435.00	X NN
1	Front wheel hub bearing LH	Bent	\$ 663.00	\$ 663.00	X NN
1	Front wheel shock absorber LH	Bent	\$ 638.00	\$ 638.00	X NN
			\$ 7,931.00	\$ 7,411.00	
Less 25%			\$ 1,982.75	\$ 1,852.75	
			\$ 5,948.25	\$ 5,558.25	

SPECIAL NETT ITEMS

1	Front bumper clips (1 set)	Necessary	\$ 100.00	\$ 100.00	30
1	Front wheel sports rim LH	Cut	\$ 680.00	\$ 680.00	X R
1	Front wheel tyre LH	Torn	\$ 200.00	\$ 200.00	X NN
			\$ 980.00	\$ 980.00	
Total parts			\$ 6,928.25	\$ 6,538.25	

J&M CONSULTANCY PTE LTD

Vehicle Registration No: SMW 7583 M

Our Ref No: ATEC/01/0003/JM

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

Total cost of parts c/f

\$ 6,928.25

\$ 6,538.25

LABOUR

1	To cut, weld, straighten affected areas and replace damaged parts.	\$ 2,800.00	\$ 2,600.00	2001- 400
2	To putty and spray painting the affected areas. Job Allowance.	\$ 2,800.00	\$ 2,600.00	2001- 200
3	To check front lighting and wiring.	\$ 150.00	\$ 120.00	30
4	To apply anti rust proofing to the affected areas.	\$ 300.00	\$ 280.00	X
5	To remove and install front garnish and trim to facilitate the repair.	\$ 180.00	\$ 160.00	X
6	To remove and install front bumper assy.	\$ 180.00	\$ 160.00	X
7	To remove and install front bumper grilles.	\$ 180.00	\$ 160.00	X
8	To remove and install headlamps.	\$ 180.00	\$ 160.00	X
9	To remove and install signal lamp & fog lamps.	\$ 180.00	\$ 160.00	X
10	To remove and install damaged wheel components.	\$ 180.00	\$ 160.00	X
11	To conduct wheel alignment	\$ 380.00	\$ 350.00	X

Grand Total:

\$ 14,438.25

\$ 13,448.25

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 10,700**

2 days. 4 days

J&M CONSULTANCY PTE LTD

Vehicle Registration No: SMW 7583 M

Our Ref No: ATEC/01/0003/JM

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

J&M Consultancy Pte Ltd



Joel Liew Jian Xiang
Automotive Appraiser