

ASS. REC. BY:

REF:

Asm / 220051111kgc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 2771M

Yr Regn:

03, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

(A) Hiac DX

c.c

2734

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

59207

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GD14201. 2011046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Dun

195R15X8

R:

Rf

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal:

8

Dun

mm

Rear

R/Bal:

B.5

6

mm

L/Bal:

6

nil

mm

L/Bal:

Dun

8

mm

D.O.A.

28/5/2

D.O.I.

31/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 G/A not ready

9/1 11 Rmp @ 5300h. Cash (Paid @ 14057.19, 73%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 20/2 typing

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS \$

) Fuel

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

SMART Clarity-TP

Lump Sum / I.B.A. (\$

5300

TOTAL

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 30 / 05 / 2022

ESTIMATE COSTS OF REPAIR

M/s Hock Yu Seng Funeral Sercives

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*Not with order
C/By @ 5300h
Mummy After Pain
7 days*

Dear Sir / Madam ,

Vehicle no. : GBK 2771 M - Toyota Hiace

Accident date : 28 / 05 / 2022

Quantity	Descriptions	Amount (S\$)
1	1 pc n/s step panel	\$ 1,245.60 X
2	1 pc n/s step panel garnish	\$ 703.40 X
3	1 pc n/s rear fender	\$ 1,321.80 ✓
4	1 pc n/s rear fender inner pillar	\$ 1,370.90 X
5	1 pc n/s rear fender centre roller rail	\$ 494.80 X
6	1 pc n/s rear fender inner garnish (inner twin board)	\$ 158.60 X
7	1 pc n/s rear mud flap	\$ 105.60 X
8	1 pc n/s rear shock absorber	\$ 113.70 X
9	1 pc n/s rear ^{drive} shaft	\$ 858.40 X
10	1 pc n/s sliding door inner lock sensor	\$ 1,049.14 X
11	1 pc n/s sliding door rubber (near door)	\$ 1,067.00 X
12	1 pc n/s sliding door rubber (near body) 287	\$ 370.40 ✓
13	1 pc n/s sliding door top garnish	\$ 271.90 X
14	1 pc n/s sliding door 1611	\$ 1,919.40 ✓
15	1 pc n/s sliding door glass	\$ 685.50 X
16	1 pc n/s sliding door inner trim board	\$ 536.80 X
17	1 pc n/s sliding door top roller	\$ 98.50 X
18	1 pc n/s sliding door centre roller	\$ 161.60 X
19	1 pc n/s sliding door bottom roller	\$ 320.40 X
20	1 pc n/s sliding door centre lock 288	\$ 804.70 ✓
21	1 pc n/s sliding door inner lock (front)	\$ 189.60 X
22	1 pc n/s sliding door inner lock (rear)	\$ 595.50 X
23	1 pc n/s rear wheel cap	\$ 175.90 ✓
24	1 pc n/s rear wheel bearing	\$ 150.70 ✓
	Balance C/FD	\$ 14,769.84

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

		Balance B/FD (GBK 2771 M)	\$ 14,769.84
25	1 pc	n/s rear wheel rim	\$ <i>sn</i> 365.40 X
		Less 25%	\$ 15,135.24
			\$ 3,783.81
			\$ 11,351.43
26	1 pc	n/s rear wheel tyre	\$ <i>sn</i> 285.00 sn X
27	1 pc	body lettring	(Bill) \$ <i>sn</i> 850.00 sn 3000
			\$ 12,486.43
		Labour charges	\$ 2,800.00 <i>800</i>
		To putty and spray painting	\$ 1,200.00 <i>600</i>
		Re-seal anti rust	\$ 250.00 <i>60</i>
		To check, replace,repair wiring ,reset fault code	\$ <i>nn</i> 120.00 X
		Remove and refix undercarriage	\$ 450.00 <i>800</i>
		To check wheel alignment	\$ 120.00 <i>60</i>
		Remove and refix interior wooden panel	\$ <i>nn</i> 350.00 X
		To transfer n/s sliding door	\$ 160.00 <i>60</i>
		Plus : 7% GST	\$ 17,936.43
		Sub_Total	\$ 1,255.55
			\$ 19,191.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 01 / 06 / 2022

RE : Supplementary

M/s Hock Yu Seng Funeral Sercives

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : GBK 2771 M - Toyota Hiace

Accident date : 28 / 05 / 2022

Quantity		Descriptions	Amount (S\$)
1	1 pc	n/s sliding door 1602. Less 25%	\$ 1,894.35 ✓ \$ 473.59 \$ 1,420.76