



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOH CYNTHIA			Ref: CS/ASM22005111/Kqcm4 Date: 22/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1807Y	Veh. Inspected	GBK 2771M
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M042KZ	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	30/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE DX (A)	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GDH2012011048	Colour	SILVER
	Odometer	59207 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	DUNLOP	8 mm
	L/H Front Tyre	195 R15X8	MICHELIN	6 mm
	R/H Rear Tyre	195 R15X8	BRIDGESTONE	6 mm
	L/H Rear Tyre	195 R15X8	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/05/2022	Inspection Date	31/05/2022
	Survey held at	H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	