

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4588J

| Qty | Description of Parts  | Condition     | Estimate By<br>Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|------------------------------|-------------------|
|     | REPLACEMENT OF PARTS  |               |                              |                   |
| 1   | COVER, RR BUMPER ASSY (DISC 25%)                            | DEFORMED      | 423.90                       | 317.93            |
| 1   | REAR BUMPER REINFORCEMENT (DISC 25%)                        | BENT          | 318.80                       | 239.10            |
| 2   | PAD, RR BUMPER, RH & LH, 1 @\$3.80 (DISC 25%)               | NECESSARY     | 7.60                         | 5.70              |
| 2   | PAD, RR BUMPER, RH & LH, 2 @\$3.80 (DISC 25%)               | NECESSARY     | 7.60                         | 5.70              |
| 2   | PAD, RR BUMPER, RH & LH, 3 @\$3.80 (DISC 25%)               | NECESSARY     | 7.60                         | 5.70              |
| 3   | PAD, RR BUMPER, CTR @\$2.20 (DISC 25%)                      | NECESSARY     | 6.60                         | 4.95              |
| 2   | SEAL, RR BUMPER ARM, RH & LH @\$11.00 (DISC 25%)            | NECESSARY     | 22.00                        | 16.50             |
| 10  | CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)             | NECESSARY     | 15.00                        | 11.25             |
| 1   | GUARD, RR BUMPER, LOWER (DISC 25%)                          | DEFORMED      | 558.30                       | 418.73            |
| 1   | COVER, GUARD RR BUMPER LOWER (DISC 25%)                     | DEFORMED      | 14.80                        | 11.10             |
| 1   | NAME PLATE (HYBRID), LUGGAGE COMPARTMENT<br>DOOR (DISC 25%) | NECESSARY     | 52.30                        | 39.23             |
| 1   | NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)     | NECESSARY     | 52.30                        | 39.23             |
| 1   | EMBLEM SUB-ASSY REAR (DISC 25%)                             | NECESSARY     | 46.30                        | 34.73             |
| 1   | STRIDES LOGO (SN)   | NECESSARY     | 7.80                         | 7.80              |
| 1   | STICKER DECAL 6555 8888 (SN)                                | NECESSARY     | 21.60                        | 21.60             |
| 2   | STOPPER, RR BUMPER, RH & LH @\$4.30                         | NOT NECESSARY | 8.60                         | -                 |
| 1   | RETAINER, RR BUMPER, RH                                     | NOT NECESSARY | 112.70                       | -                 |
| 1   | RETAINER, RR BUMPER, LH                                     | NOT NECESSARY | 111.50                       | -                 |
| 1   | SEAL, RR BUMPER, RH   | NOT NECESSARY | 85.20                        | -                 |
| 1   | SEAL, RR BUMPER, LH   | NOT NECESSARY | 85.20                        | -                 |
| 1   | SENSOR REVERSE  | NOT NECESSARY | 180.00                       | -                 |
| 1   | ANTENNA, ELECTRICAL KEY                                     | NOT NECESSARY | 60.30                        | -                 |
| 2   | REAR BUMPER GROMMET SCREW @\$2.20                           | NOT NECESSARY | 4.40                         | -                 |
| 1   | LENS & BODY, REAR COMBINATION LAMP, RH                      | NOT NECESSARY | 438.10                       | -                 |
| 1   | LENS & BODY, REAR COMBINATION LAMP, LH                      | NOT NECESSARY | 438.10                       | -                 |
| 1   | LENS & BODY ASSY, RR BUMPER, LH                             | NOT NECESSARY | 486.80                       | -                 |
| 1   | COVER, REAR FLOOR UNDER, RH                                 | NOT NECESSARY | 169.50                       | -                 |
| 1   | COVER, REAR FLOOR UNDER, LH                                 | NOT NECESSARY | 234.30                       | -                 |

Report Ref No. NS/INC22005125/Rvce2



## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

1,450.00

| Qty         | Description of Parts  | Condition               | Estimate By<br>Workshop (\$) | Our Adjusted (\$) |
|-------------|---|-------------------------|------------------------------|-------------------|
| 1           | COVER, REAR FLOOR UNDER CENTER  | NOT NECESSARY           | 222.60                       | -                 |
| 1           | TAIL GATE PANEL SUB-ASSY, BACK DOOR   | NOT NECESSARY           | 929.60                       | -                 |
| 1           | TAIL GATE WEATHERSTRIP, BACK DOOR   | NOT NECESSARY           | 360.70                       | -                 |
| 1           | TAIL GATE LOCK ASSY, BACK DOOR  | NOT NECESSARY           | 452.10                       | -                 |
| 1           | TAIL GATE LOCK COVER, BACK DOOR   | NOT NECESSARY           | 25.30                        | -                 |
| 2           | TAIL GATE BACK DOOR HINGE ASSY, RH & LH @\$59.10  | NOT NECESSARY           | 118.20                       | -                 |
| 1           | END PANEL SUB-ASSY, BODY LOWER BACK   | NOT NECESSARY           | 629.80                       | -                 |
| 1           | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY  | TO REPAIR SEE<br>LABOUR | 891.20                       | -                 |
| 1           | LENS & BODY ASSY, RR BUMPER, RH   | NOT NECESSARY           | 486.80                       | -                 |
|             |   |                         | 8,093.50                     | 1,179.25          |
|             | <u>LABOUR</u>   |                         |                              |                   |
|             | PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY. |                         | 676.00                       | 300.00            |
|             | SPRAY PAINT.  |                         | 1,296.00                     | 300.00            |
|             | TO WASH AND VACUUM.   | NOT NECESSARY           | 60.00                        | -                 |
|             | TO CHECK WIRING AND SYSTEM FUNCTION.  | NOT NECESSARY           | 120.00                       | -                 |
|             | TO APPLY RUST-PROOFING ON AFFECTED AREA.  | NOT NECESSARY           | 100.00                       | -                 |
|             | TO TEST AND REFIX REVERSE SENSOR SYSTEM.  |                         | 120.00                       | 40.00             |
|             | TO REPLACE SUNDRY PARTS.  | NOT NECESSARY           | 100.00                       | -                 |
|             |   |                         | 2,472.00                     | 640.00            |
| GRAND TOTAL |   |                         | 10,565.50                    | 1,819.25          |

Report Ref No. NS/INC22005125/Rvce2

MOHAMMED RASUL BIN MOHD YUNUS

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)

**Automotive Assessor** 

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**