



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 5428T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | HANDLE BAR | USABLE | 107.00 | - |
| 1 | MIRROR ASSY RH | CUT | 175.00 | 175.00 |
| 1 | FRONT FENDER ASSY | USABLE | 276.00 | - |
| 1 | FRONT INNER FENDER | CUT | 142.00 | 142.00 |
| 1 | INNER SHIELD TOP COVER | WARPED | 56.00 | 56.00 |
| 1 | INNER SHIELD NECK GUARD COVER | CRACKED | 113.00 | 113.00 |
| 1 | FRONT SIDE COVER RH | CRACKED | 218.00 | 218.00 |
| 1 | FRONT SIDE INNER COVER RH | CUT | 13.00 | 13.00 |
| 1 | FLOOR STEP RH | CUT | 214.00 | 214.00 |
| 1 | SET FLOOR MAT RH | NECESSARY | 161.00 | 161.00 |
| 1 | FLOOR STEP FRONT SIDE COVER RH | CUT | 217.00 | 217.00 |
| 1 | FLOOR STEP SIDE COVER RH | GRAZED | 125.00 | 125.00 |
| 1 | PILLION STEP ASSY RH | USABLE | 154.00 | - |
| 1 | REAR BODY COVER SET RH | GRAZED | 211.00 | 211.00 |
| 1 | REAR BODY COVER EMBLEM RH | NECESSARY | 38.00 | 38.00 |
| 1 | REAR FENDER | NOT NECESSARY | 95.00 | - |
| 1 | EXHAUST MUFFLER COMPLETE | CUT | 1,305.00 | 800.00 |
| 1 | MUFFLER PROTECTOR, METAL | CUT | 102.00 | 102.00 |
| 1 | MUFFLER PROTECTOR, BLACK | CUT | 63.00 | 63.00 |
| | LESS 10% DISCOUNT | | -378.50 | -264.80 |
| | | | 3,406.50 | 2,383.20 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET STEERING CONE & BEARING (SN) | NOT NECESSARY | 100.00 | - |
| 1 | REAR TOP BOX (SN) | CUT | 715.00 | 400.00 |
| | | | 815.00 | 400.00 |
| <u>LABOUR</u> | | | | |
| | REPAIR SOUNDED FORKS, ALIGN STEERING COMPONENTS. | NOT NECESSARY | 200.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|-----------|---------------------------|-------------------|
| | RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS. | | 450.00 | 300.00 |
| | | | 650.00 | 300.00 |
| GRAND TOTAL | | | 4,871.50 | 3,083.20 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 2,450.00 |

Report Ref No. CS3/ASM22002678/Evy3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.