

TPAXA.
Veron.

SKP8708A. 2014 Oct.

Mercedes Benz E250 1981cc

WDD2120362B047911

Rear Bumper Deformed	1510 ✓
Rear Bumper clips - Nec	50 ✓
Rear Bumper Side Holder x 02 ^{Nec}	59 x 2 = 118 ✓
Rear Bumper Lower Garnish Deformed	336 ✓
Rear Bumper Lower Garnish Chrome Moulding ^{at}	258 ✓
Rear Bumper Reinforcement Dented.	764 ✓
Rear Bumper Centre Guide. Crushed.	185 ✓
Rear Bumper Exhaust Chrome Pipe x 02 ^{Dented}	266 x 2 = 532 ✓
Rear Bumper Lower Kick Sensor Bracket ^{Dmg}	102 ✓
Rear Bumper Lower Side Bracket x 02 ^{Dmgd}	69 x 2 = 138 ✓
Reverse Sensor x 04 2 pieces dmgd	250 x 4 = 1000 500.
Tail Lamp x 02	645 x 2 = 1290 x
Tail Lamp Bracket x 02	75 x 2 = 150 x

6433

4473

402570

SKP8708A.

Panel Beating

Spray Painting

Wiring.

To remove sensor

To perform diagnostic test

630

~~500~~ 300

~~400~~ 250

~~50~~ 30

~~100~~ 50

200. X.

1250

7683

Total: 4655.70

L/s: 3.7K.

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: