

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22005136/TQCM4**Date:** 03/08/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000479		
Claimant Vehicle No :	SHB2451M	Insured Vehicle No :	SMN9111B		
Date of Loss:	30/05/2022	Nature of Claim:	TP	Claim No:	M2202756

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2451M	Engine No:	G4LEJU111406
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU114874
Reg. Date:	18/10/2018 (Man. Year: 2018)	Odometer:	367051 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,758.60	1,075.16	683.44	38.86
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	800.00	630.00	170.00	21.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,569.60	1,716.16	853.44	33.21
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	2,569.60	1,350.00	1,219.60	47.46
+ GST 7.00/7.00% (S\$)	179.87	94.50	85.37	47.46
Nett Amount (S\$)	2,749.47	1,444.50	1,304.97	47.46

INSPECTION

Date of Assignment:	31/05/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	31/05/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Aug 2022)

Parts: 143 HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB2451M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER MAT	Not Necessary	50.00 F	*- F
4	1		*REAR BUMPER CENTRE MOULDING	Cracked	451.25 FL	*451.25 FL
5	1		*REAR BUMPER CENTRE LOWER MOULDING	Not Necessary	155.00 FL	*- FL
6	1		*REAR BUMPER TOW COVER	Deformed	98.80 FL	*98.80 FL
7	1		*REAR NUMBER PLATE	Cracked	50.00 F	*50.00 F
8	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
9	1		*REAR FOG LAMP	Not Necessary	201.50 FL	*- FL
10	1		*ANTENNA ASSY - SMARTK	Not Necessary	40.50 FL	*- FL
11	1		*ADVERTISEMENT LOGO - FENDER	Necessary	200.00 F	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,123.25	1,281.45
- List Item Discount on L Items 20.00/20.00% (\$\$)	364.65	206.29
Total Parts (\$\$)	1,758.60	1,075.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	CHECK WIRING	New	50.00	0.00
4	REMOVE/REFRIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			800.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >