

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 8118M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT LH FENDER | BENT | 1,418.00 | 1,012.35 |
| 1 | FRT WHEEL ARCH PROTECTOR | TORN | 165.00 | 165.00 |
| 1 | FRONT BUMPER ASSY | DEFORMED | 1,786.00 | 1,503.60 |
| 1 | FRT LH RETAINER | DEFORMED | 75.00 | 75.00 |
| 1 | LH H/LAMP ASSY | CRACKED | 5,975.00 | 4,845.10 |
| 1 | LH H/LAMP BRACKET | NOT NECESSARY | 245.00 | - |
| 1 | FRONT LH LOWER COVER | NOT NECESSARY | 115.00 | - |
| 1 | FRT LH CONTROL ARM | NOT NECESSARY | 685.00 | - |
| 1 | FRT LH TRACTION ARM | NOT NECESSARY | 589.00 | - |
| 1 | FRT LH UPPER ARM | NOT NECESSARY | 648.00 | - |
| 1 | SET FRT LH HUB & BEARING | BENT | 615.00 | 615.00 |
| 1 | SET FRT LH WHEEL KNUCKLE ASSY | BENT | 775.00 | 775.00 |
| | LESS 10% DISCOUNT | | - | -899.10 |
| | | | 13,091.00 | 8,091.95 |
| | SPECIAL NETT ITEMS | | | |
| 1 | PDC SENSOR (SN) | NOT WORKING | 225.00 | 200.00 |
| 1 | TYRE 19" GOODYEAR 245/45/R19 (SN) (80%) | сит | 385.00 | 308.00 |
| 1 | ORIGINAL RIM 19" BMW (SN) | DENTED | 2,200.00 | 1,000.00 |
| 1 | SET BUMPER CLIPS & FASTENERS (SN) | NECESSARY | 120.00 | 40.00 |
| 1 | SET FENDER CLIPS & FASTENERS (SN) | NECESSARY | 80.00 | 40.00 |
| | | | 3,010.00 | 1,588.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING AFFECTED PANELS. | | 800.00 | 500.00 |
| | SPRAY PAINTING AFFECTED PANELS. | | 1,100.00 | 500.00 |
| | CHECK WIRING. | | 180.00 | 50.00 |
| | DIAGNOSTICS "BMW". | | 250.00 | 150.00 |
| | WHEEL ALIGNMENT. | | 160.00 | 80.00 |
| | RENEW / REFIT PARKING PDC SENSORS. | | 80.00 | 40.00 |

Report Ref No. CS/SMR22005140/Tvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

8,800.00

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--------------------------|-----------|-------------------------------|-------------------|
| | PAINT PROTECTION SYSTEM. | | 880.00 | - |
| | | | 3,450.00 | 1,320.00 |
| _ | GRAND TOTAL | | 19,551.00 | 10,999.95 |

Report Ref No. CS/SMR22005140/Tvy3m4

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.