

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22005146/UQY3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00031872200  
**Claimant Vehicle No :** SMU1395P **Insured Vehicle No :** SLM7171H  
 Date of Loss: 07/05/2022 Nature of Claim: TP Claim No: SNM22D203526/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU1395P**  
 Make & Model: NISSAN SERENA, 1.2 L HIGHWAY STAR PREMIUM E-POWER (A) Engine No: HR12187507K  
 Reg. Date: 23/07/2020 (Man. Year: 2020) Chassis No: JN1EBAC27Z0000661  
 Colour: Grey Odometer: 103450 km  
 Engine Capacity: 1198 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16  
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm  
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,032.40	8,370.32	1,662.08	16.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,355.00	1,985.00	1,370.00	40.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,387.40</b>	<b>10,355.32</b>	<b>3,032.08</b>	<b>22.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>937.12</b>	<b>724.87</b>	<b>212.25</b>	<b>22.65</b>
<b>Nett Amount (S\$)</b>	<b>14,324.52</b>	<b>11,080.19</b>	<b>3,244.33</b>	<b>22.65</b>

INSPECTION

Date of Assignment: 31/05/2022  
 Date Inspected: 01/06/2022 Inspected At: Autolution Industrial Pte Ltd (Ubi)  
 19 Ubi Road 4  
 Singapore 408623  
 Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2022)

**Parts:** M1-MPV NISSAN SERENA 1.2 L HIGHWAY STAR PREMIUM E-POWER (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMU1395P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR W/SCREEN PANEL/OWER CHROME MOULDING	Grazed	860.70 FN	*860.70 FN
2	1		*TAIL GATE HANDLE MOULDING -SERENA	Grazed	860.70 FN	*860.70 FN
3	1		*REAR PANEL	Repair	232.40 FN	*- FN
4	1		*BOX-LUGGAGE	Not Necessary	302.00 FN	*- FN
5	1		*LUGGAGE CARPET	Not Necessary	570.00 FN	*- FN
6	1		*TRUNK TOP PLATE	Not Necessary	56.50 FN	*- FN
7	1		*STRIKER -TAIL GATE	Not Necessary	37.60 FN	*- FN
8	1		*TAIL GATE LOCK	Not Necessary	215.60 FN	*- FN
9	1		*EMBLEM REAR E-POWER	Necessary	101.90 FN	*101.90 FN
10	1		*EMBLEM -REAR HIGHWAY STAR EMBLEM	Necessary	54.90 FN	*54.90 FN
11	1		*TAIL GATE NISSAN EMBLEM	Necessary	86.20 FN	*86.20 FN
12	1		*TAIL GATE BACK DOOR	Dented	1,880.40 FN	*1,880.40 FN
13	10		*CLIP REAR BUMPER	Necessary	14.00 FN	*14.00 FN
14	1		*REAR BUMPER FASCIA	Deformed	1,527.10 FN	*1,527.10 FN
15	1		*SUNDIES	Necessary	50.00 FS	*20.00 FS
16	1		*REAR LICENCE PLATE	Scratched	60.00 FS	*60.00 FS
17	2		*REVERSE SENSOR HOLDER	Necessary	156.60 FS	*156.60 FS
18	2		*REVERSE SENSOR	Serviceable	500.80 FS	*- FS
19	1		*REAR WINDSCREEN SOLAR FILM	Necessary	150.00 FS	*150.00 FS
20	1		*REAR WINDSCREEN GLASS W/GARNISH	Cut	4,334.00 FN	*4,334.00 FN
21	1		*LH SIDE CORNER INNER BRACKET REVERSE SENSOR	Necessary	103.90 FS	*103.90 FS
22	1		*RH SIDE CORNER INNER BRACKET REVERSE SENSOR	Necessary	103.90 FS	*103.90 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,259.20</b>	<b>10,314.30</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	2,226.80	1,943.98
<b>Total Parts (\$\$)</b>	<b>10,032.40</b>	<b>8,370.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR CHARGES TO REPAIR TRUNK FLOOR ,RENEW REAR PANEL ,REAR BUMPER AND TAIL GATE BACK DOOR	New	1,500.00	700.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,200.00	750.00
3	REMOVE AND INSTALL REVERSE SENSOR -RENEW IF NEC	New	110.00	110.00
4	APPLY SEALANT TO TAIL GATE BACK DOOR	New	100.00	100.00
5	PERFORM RUST PROOFING TO REAR PANEL	New	120.00	0.00
6	REMOVE AND INSTALL REAR WINDSCREEN DOOR PANEL ,FINISHER MOUNTING AND RESET REVERSE CAMERA	New	245.00	245.00
7	SUPPLY REAR LICENCE PLATE (NPA)	New	0.00	0.00
8	REMOVE AND INSTALL TAIL GATE DOOR MECHANISM	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,355.00</b>	<b>1,985.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >