

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 3973H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR END PANEL	DENTED	329.10	329.10
1	REAR NUMBER PLATE LAMP	SERVICEABLE	145.00	-
2	REAR TAILLAMP L/R @\$298.10	CRACKED	596.20	596.20
	LESS 10% DISCOUNT		-107.03	-92.53
			963.27	832.77
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
1	SET REAR REVERSE SENSOR (SN)	CUT	280.00	200.00
1	REAR TAILGATE '70KM' STICKER (SN)	NECESSARY	25.00	25.00
1	REAR TAILGATE (ALUMINIUM) (SN)	DENTED	2,000.00	1,400.00
			2,330.00	1,650.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		80.00	30.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,000.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	30.00
			2,180.00	1,060.00
	GRAND TOTAL		5,473.27	3,542.77

RECOMMENDED COST OF LUMP SUM REPAIRS		2,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22005147/Vny3e2

B

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

X:2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.