

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005149/KVY3M4**Date:** 10/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00016222201
Claimant Vehicle No :	SGF1879K	Insured Vehicle No :	GBF7430R
Date of Loss:	27/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203728/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF1879K	Engine No:	1ZZ2473174
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100286840
Reg. Date:	03/04/2006 (Man. Year: 2005)	Odometer:	182021 km
Colour:	Metallic Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,502.43	3,751.67	6,750.76	64.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	2,460.00	1,280.00	34.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,242.43	6,211.67	8,030.76	56.39
Approved Total (Overridden) (\$\$)		4,950.00		
(\$\$)	14,242.43	4,950.00	9,292.43	65.24
+ GST 7.00/7.00% (\$\$)	996.97	346.50	650.47	65.24
Nett Amount (\$\$)	15,239.40	5,296.50	9,942.90	65.24

INSPECTION

Date of Assignment:	31/05/2022	
Date Inspected:	31/05/2022 Inspected At:	ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF1879K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Bent	1,121.50 FL	*723.40 FL
2	1		*FRONT LH FENDER INNER SHIELD	Distorted	232.10 FL	*181.00 FL
3	1		*LH SIDE MIRROR ASSY	Broken	1,312.00 FL	*680.40 FL
4	1		*FRONT LH DOOR	Bent	2,140.00 FL	*1,109.00 FL
5	1		*FRONT LH DOOR HINGE	Bent	101.50 FL	*101.50 FL
6	1		*FRONT LH DOOR CHECKER	Serviceable	210.00 FL	*- FL
7	1		*FRONT LH DOOR RUBBER @ BODY	Serviceable	380.00 FL	*- FL
8	1		*FRONT LH DOOR INNER TRIM BOARD	Serviceable	1,080.50 FL	*- FL
9	1		*FRONT LH DOOR WINDOW REGULATOR	Bent	216.70 FL	*216.70 FL
10	1		*REAR LH DOOR	Bent	1,981.00 FL	*1,089.50 FL
11	1		*REAR LH DOOR HINGE	Bent	101.50 FL	*101.50 FL
12	1		*REAR LH DOOR CHECKER	Repair	200.30 FL	*- FL
13	1		*REAR LH DOOR RUBBER @ BODY	Serviceable	1,010.80 FL	*- FL
14	1		*REAR LH DOOR RUBBER	Serviceable	273.00 FL	*- FL
15	1		*REAR LH DOOR INNER TRIM BOARD	Serviceable	680.30 FL	*- FL
16	1		*REAR LH DOOR WINDOW REGULATOR	Repair	216.70 FL	*- FL
17	1		*REAR RH FENDER	Repair	1,445.60 FL	*- FL
18	1		*REAR RH FENDER INNER SHIELD	Serviceable	60.80 FL	*- FL
19	1		*RH ROCKER PANEL	Bent	386.50 FL	*386.50 FL
20	1		*FRONT LH DOOR RUBBER (50%)	Dented / Cut	179.33 FS	*119.55 FS
21	1		*SET FRONT LH & REAR LH FENDER SHIELD CLIPS	Necessary	70.00 FS	*70.00 FS
22	1		*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	45.00 FS	*- FS
23	1		*SET REAR LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	45.00 FS	*- FS
24	1		*SET WINDOW VISOR	Necessary	300.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **13,790.13** **4,899.05**

- List Item Discount on L Items 25.00/25.00% (\$\$) **3,287.70** **1,147.38**

Total Parts (\$\$) **10,502.43** **3,751.67**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA.	New	1,500.00	1,200.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.	New	1,500.00	1,000.00
3	TO CHECK WIRING SYSTEM & LIGHT.	New	120.00	20.00
4	TO APPLY ANTI RUST TREATMENT.	New	120.00	120.00
5	TO REMOVE/REFIX FRONT & REAR LH DOOR GLASS, INNER COMPARTMENT, MECHANISM & ETC TO NEW DOOR.	New	400.00	120.00
6	TO CHECK & ADJUST WHEEL ALIGNMENT.	New	100.00	0.00
Gross Labour Cost (\$\$)			3,740.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >