

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005153/KEA3Q2**Date:** 21/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100465598
Claimant Vehicle No :	SHB5102B	Insured Vehicle No :	SLC3576C
Date of Loss:	28/05/2022	Nature of Claim:	TP
		Claim No:	7212475672SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5102B		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G83670
Reg. Date:	30/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU503091652
Colour:	Metallic Brown	Odometer:	115789 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 7 mm	Rear Left Side:	Farroad 9 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Farroad 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,408.60	1,187.49	12,221.11	91.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	870.00	2,300.00	72.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	16,578.60	2,057.49	14,521.11	87.59
+ Car Rental (5.0 x S\$73.00/day) (S\$)		365.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,429.49		
Global Sum Settlement (S\$)		2,420.00		

INSPECTION

Date of Assignment:	31/05/2022	
Date Inspected:	31/05/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PAD ,RR BUMPER ,RH & LH ,2 (DISC 25%)	Necessary	8.00 F	*6.00 F
2	2		*PAD ,RR BUMPER ,RH & LH ,1 (DISC 25%)	Necessary	8.00 F	*6.00 F
3	3		*PAD ,RR BUMPER ,CTR (DISC 25%)	Necessary	33.00 F	*24.75 F
4	1		*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	22.60 F	*16.95 F
5	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
6	1		*COVER ,RR BUMPER ASSY (DISC 25%)	Buckled	485.60 F	*364.20 F
7	2		*PAD ,RR BUMPER ,RH & LH 3 (DISC 25%)	Necessary	22.00 F	*16.50 F
8	1		*GUARD ,RR BUMPER LOWER (DISC 25%)	Bent	374.50 F	*280.88 F
9	1		*COVER ,GUARD RR BUMPER LOWER (DISC 25%)	Necessary	22.00 F	*16.50 F
10	1		*COVER ,REAR FLOOR UNDER CENTER (DISC 25%)	Missing	229.90 F	*172.43 F
11	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Bent	332.70 F	*249.53 F
12	1		*MOULDING SUB-ASSY ,ROOF TOP	Not Necessary	656.90 F	*- F
13	1		*EMBLEM SUB-ASSY REAR	Not Necessary	47.90 F	*- F
14	1		*TAIL GATE LOCK COVER ,BACK DOOR	Not Necessary	30.20 F	*- F
15	1		*TAIL GATE LOCK ASSY ,BACK DOOR	Not Necessary	467.00 F	*- F
16	1		*TAIL GATE WEATHERSTRIP BACK DOOR	Not Necessary	372.30 F	*- F
17	1		*COVER REAR COMBINATION LAMP ,LH	Not Necessary	69.90 F	*- F
18	1		*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
19	2		*STOPPER ,RR BUMPER ,RH & LH	Not Necessary	4.50 F	*- F
20	1		*RETAINER ,RR BUMPER ,RH	Not Necessary	132.60 F	*- F
21	1		*RETAINER ,RR BUMPER ,LH	Not Necessary	132.60 F	*- F
22	1		*SEAL ,RR BUMPER ,RH	Not Necessary	118.30 F	*- F
23	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,RH	Not Necessary	39.00 F	*- F
24	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,LH	Not Necessary	39.00 F	*- F
25	1		*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	241.90 F	*- F
26	1		*LENS & BODY REAR COMBINATION LAMP ,RH	Not Necessary	339.60 F	*- F
27	1		*LENS & BODY REAR COMBINATION LAMP ,LH	Not Necessary	339.60 F	*- F
28	1		*COVER ,REAR COMBINATION LAMP RH	Not Necessary	69.90 F	*- F
29	1		*LENS & BODY ,REAR COMBINATION LAMP NO.2	Not Necessary	261.00 F	*- F
30	1		*LENS & BODY ,REAR COMBINATION LAMP NO.2	Not Necessary	261.00 F	*- F
31	1		*LENS ASSY ,REAR RH	Not Necessary	293.60 F	*- F
32	1		*LAMP ASSY ,REAR LH	Not Necessary	293.60 F	*- F
33	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
34	1		*TAIL GATE GLASS SUB-ASSY ,BACK DOOR	Not Necessary	1,656.70 F	*- F
35	1		*TAIL GATE LOWER GLASS SUB-ASSY ,BACK DOOR	Not Necessary	761.40 F	*- F
36	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	Not Necessary	913.60 F	*- F
37	2		*TAIL GATE BACK DOOR HINGE ASSY RH & LH	Not Necessary	61.00 F	*- F
38	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
39	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F
40	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	Not Necessary	54.60 F	*- F
41	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Not Necessary	913.60 F	*- F
42	1		*COVER ,TAIL GATE BACK DOOR GARNISH	Not Necessary	8.50 F	*- F
43	1		*STRIDES LOGO	Not Necessary	7.80 F	*- F
44	1		*STICKER DECAL 65558888	Not Necessary	21.60 F	*- F
45	1		*REAR BUMPER REINFORCEMENT	Not Necessary	332.70 F	*- F
46	1		*TAIL GATE MOULDING GLASS ,BACK DOOR	Not Necessary	35.50 F	*- F
47	1		*SEAL ,RR BUMPER ,LH	Not Necessary	118.30 F	*- F
48	1		*COVER ,REAR FLOOR UNDER RH	Serviceable	175.10 F	*- F
49	1		*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
50	1		*ANTENNA ELECTRICAL KEY	Serviceable	72.00 F	*- F
51	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
52	1		*END PANEL SUB-ASSY BODY LOWER BACK	Repair	651.00 F	*- F
53	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Repair	1,147.80 F	*- F

F=Franchise part.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$\$)	13,408.60
						1,187.49
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	400.00
2	SPRAY PAINT	New	1,296.00	400.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	20.00
5	TO APPLY RUST -PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	50.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			3,170.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >