



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 9103G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	REAR NUMBER PLATE LAMP @\$68.00	NOT NECESSARY	176.00	-
1	REAR BUMPER	DEFORMED	1,122.00	1,122.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	546.00	-
1	REAR BUMPER COVER GARNISH	CUT	395.00	395.00
2	REAR BUMPER REFLECTOR @\$89.00	NOT NECESSARY	178.00	-
1	REAR BUMPER CENTRE GUIDE	CRACKED	230.00	230.00
2	REAR BUMPER SIDE HOLDER @\$72.00	NECESSARY	142.00	142.00
2	TAILLAMP @\$485.00	O/S CRACKED	970.00	485.00
	LESS 10% DISCOUNT		-	-237.40
			3,759.00	2,136.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	30.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			370.00	230.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		400.00	300.00
	SPRAY PAINTING.		400.00	250.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
			950.00	630.00
<b>GRAND TOTAL</b>			<b>5,079.00</b>	<b>2,996.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,400.00</b>

Report Ref No. CS/AGI22005157/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.