

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005158/BVY3E2
Date: 20/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00010752204
Claimant Vehicle No :	GBJ8269M	Insured Vehicle No :	GBH1508E
Date of Loss:	29/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203801/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ8269M	Engine No:	D4CBK856292
Make & Model:	KIA K2500 6M/T, 2.5 D (M)	Chassis No:	KNCSJX76LK7382987
Reg. Date:	29/08/2019 (Man. Year: 2019)	Odometer:	56692 km
Colour:	Blue		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,532.32	7,427.44	28,104.88	79.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,500.00	2,930.00	7,570.00	72.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,032.32	10,357.44	35,674.88	77.50
Approved Total (Overridden) (S\$)		8,300.00		
	(S\$)	8,300.00	37,732.32	81.97
	+ GST 8.00/8.00% (S\$)	664.00	3,018.59	81.97
	Nett Amount (S\$)	8,964.00	40,750.91	81.97

INSPECTION

Date of Assignment:	01/07/2022		
Date Inspected:	31/05/2022	Inspected At:	Team Autopro Pte Ltd (Sin Ming) 160 Sin Ming Dr #01-14 Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	12.0 days		

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jan 2023)	
Parts:	N/A	KIA K2500 6M/T 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ8269M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Dented	1,372.30 FL	*1,050.00 FL
2	1		*REAR GATE EMBLEM C&C	Necessary	198.30 FL	*80.00 FL
3	1		*REAR GATE HINGES (4PCS)	Bent(3Pcs Only)	348.80 FL	*261.60 FL
4	2		*REAR GATE LATCH LOCK	Not Damaged	213.00 FL	*- FL
5	2		*REAR GATE SIDE LOCK COVER	Not Damaged	111.20 FL	*- FL
6	2		*REAR GATE STOPPER RUBBER	Not Damaged	77.20 FL	*- FL
7	1		*REAR END PANEL	Dented	718.60 FL	*595.00 FL
8	1		*REAR STEP MEMBER	Bent	2,365.80 FL	*900.00 FL
9	1		*REAR NO PLATE BRACKET	Bent	145.50 FL	*145.50 FL
10	2		*REAR NO PLATE LAMP	Broken	129.00 FL	*129.00 FL
11	1		*REAR TOW HOOK	No such part	85.00 FL	*- FL
12	2		*SIDE GATE	Not Damaged	5,105.80 FL	*- FL
13	2		*SIDE GATE LOCK FRONT	Not Damaged	311.80 FL	*- FL
14	2		*SIDE GATE LOCK REAR	Not Damaged	311.80 FL	*- FL
15	10		*SIDE GATE HINGE	Not Damaged	872.00 FL	*- FL
16	2		*TAILLAMP	Broken	713.80 FL	*713.80 FL
17	1		*TAILLAMP PANEL	N/S Bent	373.20 FL	*186.60 FL
18	2		*REAR FLOOR SIDE PANEL	Not Damaged	945.20 FL	*- FL
19	8		*REAR FLOOR BED MOUNTING BUSH	Not Damaged	580.00 FL	*- FL
20	1		*FRONT PANEL	Dented	876.25 FL	*760.00 FL
21	2		*FRONT CORNER PANEL	Not Damaged	578.80 FL	*- FL
22	1		*FRONT PANEL LOGO	Necessary	65.80 FL	*65.80 FL
23	1		*FRONT WIPER PANEL	Not Damaged	243.55 FL	*- FL
24	2		*FRONT WIPER PANEL SIDE GARNISH	Not Damaged	250.00 FL	*- FL
25	2		*HEADLAMP	Broken	1,708.40 FL	*1,300.00 FL
26	1		*FRONT BUMPER	Broken	456.20 FL	*456.20 FL
27	1		*FRONT BUMPER LOWER GRILLE	Broken	286.20 FL	*286.20 FL
28	2		*FRONT BUMPER BRACKET	No such part	490.60 FL	*- FL
29	2		*FRONT BUMPER COVER	No such part	156.00 FL	*- FL
30	1		*FRONT CROSS MEMBER	Bent	483.00 FL	*325.00 FL
31	1		*FRONT DOOR LH	Not Damaged	1,208.60 FL	*- FL
32	1		*FRONT DOOR LOCK LH	Not Damaged	236.80 FL	*- FL
33	2		*FRONT DOOR HINGE LH	Not Damaged	156.00 FL	*- FL
34	1		*FRONT DOOR CENTER PILLAR LH	Not Damaged	458.60 FL	*- FL
35	1		*FRONT WINDSCREEN	Not Damaged	1,425.60 FL	*- FL
36	1		*FRONT CABIN GLASS	Broken	798.50 FL	*798.50 FL
37	1		*FRONT CABIN GLASS RUBBER	Necessary	268.60 FL	*268.60 FL
38	1		*BRAKE BOOSTER PUMP	Not Damaged	574.00 FL	*- FL
39	1		*BRAKE BOOSTER PUMP BRACKET	Not Damaged	134.50 FL	*- FL
40	1		*SPARE TYRE	Not Damaged	500.00 FL	*- FL
41	1		*SPARE TYRE HOLDER	Not Damaged	245.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT DASHBOARD FASCIA	Not Damaged	1,098.50 FL	*- FL
43	1		*FRONT DASHBOARD GLOVE BOX	Not Damaged	185.00 FL	*- FL
44	1		*A/C BLOWER ASSY	Not Damaged	1,138.00 FL	*- FL
45	1		*A/C COOLING COIL ASSY	Not Damaged	1,980.00 FL	*- FL
46	1		*WING MIRROR HOLDER BRACKET	Not Damaged	386.50 FL	*- FL
47	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
48	1		*REAR GATE STICKER	Necessary	500.00 FS	*300.00 FS
49	1		*REAR GATE STICKER 70KM/H	Necessary	30.00 FS	*10.00 FS
50	1		*REAR GATE STICKER 13 PAX	Necessary	30.00 FS	*10.00 FS
51	1		*REAR GATE ALUMINIUM PLATE	Not Necessary	800.00 FS	*- FS
52	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
53	1		*REAR STEP BRACKET	Not Damaged	250.00 FS	*- FS
54	1		*REAR FLOOR BED SEALANT	Not Damaged	100.00 FS	*- FS
55	1		*REAR FLOOR BED ALUMINIUM PLATE	Not Damaged	1,200.00 FS	*- FS
56	1		*REAR FLOOR BED ALUMINIUM PLATE RIVET NAIL	Not Damaged	120.00 FS	*- FS
57	2		*SIDE GATE CHROME BAR	Not Damaged	1,500.00 FS	*- FS
58	1		*REAR TOOLS BOX	Not Damaged	580.00 FS	*- FS
59	1		*REAR TOOLS BOX BRACKET	Not Damaged	380.00 FS	*- FS
60	1		*REAR NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS
61	2		*REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
62	2		*REVERSE SENSOR BRACKET	Not Necessary	60.00 FS	*- FS
63	1		*FRONT PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
64	1		*FRONT CORNER PANEL CLIPS	Not Necessary	50.00 FS	*- FS
65	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
66	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
67	1		*FRONT NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS
68	1		*FRONT WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
69	1		*FRONT WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
70	1		*FRONT CABIN GLASS SEALANT	Not Necessary	50.00 FS	*- FS
71	1		*FRONT CABIN GLASS PRIMER & CLEANER	Not Necessary	40.00 FS	*- FS
72	1		*ERP UNIT BRACKET	Not Necessary	30.00 FS	*- FS
73	1		*COOLANT	Necessary	80.00 FS	*30.00 FS
74	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
75	1		*AIR CON FLUID	Necessary	80.00 FS	*40.00 FS
76	1		*REAR GATE ALUMINIUM PLATE RIVETS NAIL	Not Necessary	80.00 FS	*- FS
77	1		*REAR FLOOR BED	Not Damaged	3,885.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	42,582.90	9,091.80
- List Item Discount on L Items 20.00/20.00% (\$)	7,050.58	1,664.36
Total Parts (\$)	35,532.32	7,427.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR GATE ALUMINIUM PLATE	New	250.00	0.00
2	R&R SIDE GATE CHROME BAR	New	300.00	0.00
3	R&R REAR FLOOR BED ALUMINIUM PLATE	New	450.00	0.00
4	R&R REAR CABIN	New	400.00	0.00
5	R&R REAR TOOLS BOX	New	150.00	0.00
6	R&R REVERSE SENSOR	New	100.00	60.00
7	REAR UPHOLSTERY	New	300.00	0.00
8	REAR CHECK WIRING	New	100.00	0.00
9	REAR SPARE TYRE	New	100.00	0.00
10	REAR PANEL BEAT	New	1,400.00	1,000.00
11	REAR RUST PROOFING	New	200.00	0.00
12	REAR SPRAY PAINTING	New	1,400.00	600.00
13	R&R FRONT WINDSCREEN	New	150.00	0.00
14	R&R FRONT CABIN GLASS	New	100.00	70.00
15	R&R FRONT DOOR COMPONENT	New	200.00	0.00
16	R&R BRAKE BOOSTER PUMP	New	150.00	0.00
17	R&R DASHBOARD	New	450.00	0.00
18	R&R A/C BLOWER	New	150.00	0.00
19	R&R A/C COOLING COIL	New	150.00	0.00
20	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
21	WHEEL ALIGNMENT	New	300.00	0.00
22	FRONT UPHOLSTERY	New	300.00	0.00
23	FRONT CHECK WIRING	New	100.00	0.00
24	FRONT PANEL BEAT	New	1,400.00	800.00
25	FRONT RUST PROOFING	New	200.00	0.00
26	FRONT SPRAY PAINTING	New	1,400.00	400.00
Gross Labour Cost (\$)			10,500.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >