

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005161/APA3Q2**Date:** 30/05/2023REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMS3511T**Insured Vehicle No :** GBC4889L

Date of Loss: 29/05/2022

Nature of Claim: TP

Claim No: 7571572730SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMS3511T**

Make & Model: AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)

Engine No: CZC545476

Reg. Date: 30/06/2016 (Man. Year: 2016)

Chassis No: WAUZZZ8V8GA147685

Colour: Bronze

Odometer: 76237 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R19

Rear Tyre Size: 225/40 R19

Front Left Side: Efficient 6 mm

Rear Left Side: Efficient 6 mm

Front Right Side: Efficient 6 mm

Rear Right Side: Efficient 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,826.00	5,142.48	7,683.52	59.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,202.00	3,612.00	4,590.00	55.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,028.00	8,754.48	12,273.52	58.37
+ GST 8.00/8.00% (S\$)	1,682.24	700.36	981.88	58.37
Nett Amount (S\$)	22,710.24	9,454.84	13,255.40	58.37
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,756.84		

INSPECTION

Date of Assignment: 07/06/2022

Date Inspected: 07/06/2022

Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,146.00 FS	*1,716.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	175.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE SECTION -LH	Damaged	71.00 FS	*56.48 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	122.00 FS	*- FS
6	1		*FRONT FENDER -LH	Dented	954.00 FS	*763.20 FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
8	1		*FRONT FENDER BRACKET -LH	Bent	56.00 FS	*44.40 FS
9	1		*FRONT FENDER POP RIVET (9 PCS)	Necessary	35.00 FS	*27.36 FS
10	1		*FRONT FENDER BRACE -LH	Bent	107.00 FS	*85.60 FS
11	1		*FRONT FENDER CLOSING EMBLEM -LH	Damaged	68.00 FS	*54.24 FS
12	1		*FRONT FENDER BRACKET END -LH	Not Necessary	31.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER -LH	Torn	183.00 FS	*146.40 FS
14	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
15	1		*HEADLIGHT -LH	Cut	2,810.00 FS	*2,248.00 FS
16	1		*HEADLIGHT POWER MODULE	Not Necessary	616.00 FS	*- FS
17	1		*HEADLIGHT CONTROL UNIT	Not Necessary	1,237.00 FS	*- FS
18	1		*GAS DISCHARGE LAMP	Not Necessary	453.00 FS	*- FS
19	1		*HEADLIGHT HOSE -LH	Not Necessary	60.00 FS	*- FS
20	1		*LIFT CYLINDER LH	Not Necessary	211.00 FS	*- FS
21	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
22	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
23	1		*TRACK CONTROL ARM	Not Necessary	393.00 FS	*- FS
24	1		*FRONT WHEEL BEARING HOUSING	Not Necessary	627.00 FS	*- FS
25	1		*FRONT WHEELHUB BEARING	Not Necessary	553.00 FS	*- FS
26	1		*SUSPENSION GUIDE JOINT	Not Necessary	137.00 FS	*- FS
27	1		*COUPLING ROD	Not Necessary	105.00 FS	*- FS
28	1		*GAS SHOCK ABSORBER	Not Necessary	281.00 FS	*- FS
29	1		*TRACK ROD	Not Necessary	98.00 FS	*- FS
30	1		*TIE ROD END LH	Not Necessary	126.00 FS	*- FS
31	1		*LHS FRONT RIM (NPA)	Not Necessary	0.00 FS	*- FS
32	1		*LHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
33	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **12,826.00** **5,142.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM ,TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR	New	280.00	280.00
2	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	2,400.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT RE-ORGANIZE CRASH ,MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
6	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,650.00
7	TO RENEW LHS FRONT RIM WITH TYRE ,TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	240.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,202.00	3,612.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >