

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22005165/UVY3M4**Date:** 14/07/2022**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MCF22A00000100
<b>Claimant Vehicle No :</b>	SKW1380U	<b>Insured Vehicle No :</b>	SML2739Y
Date of Loss:	18/05/2022	Nature of Claim:	TP
		Claim No:	DMCF2200060H

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKW1380U</b>		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2185451A
Reg. Date:	19/10/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1475723
Colour:	Black	Odometer:	89539 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,331.20	1,235.76	6,095.44	83.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	2,225.00	1,425.00	39.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,981.20</b>	<b>3,460.76</b>	<b>7,520.44</b>	<b>68.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	768.68	242.25	526.43	68.48
<b>Nett Amount (S\$)</b>	<b>11,749.88</b>	<b>3,703.01</b>	<b>8,046.87</b>	<b>68.48</b>

**INSPECTION**

Date of Assignment:	31/05/2022		
Date Inspected:	02/06/2022	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)

**Parts:** M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKW1380U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM REAR QASHQAI	Necessary	101.90 FN	*101.90 FN
2	1		*EMBLEM-REAR NISSAN	Necessary	70.00 FN	*70.00 FN
3	1		*STRIKER-TAIL GATE	Not Necessary	37.60 FN	*- FN
4	1		*TAIL GATE LOCK	Not Necessary	205.50 FN	*- FN
5	1		*TAIL GATE OUTER HANDLE GARNISH	Repair	380.00 FN	*- FN
6	1		*REAR W/SCREEN FASTENER	Not Necessary	68.90 FN	*- FN
7	1		*REAR WINDSCREEN GLASS	Not Necessary	1,174.80 FN	*- FN
8	1		*TAIL GATE BACK DOOR	Repair	3,636.60 FN	*- FN
9	1		*CLIP TRUNK TOP PLATE @\$1.40 EACH	Not Necessary	11.20 FN	*- FN
10	1		*TRUNK TOP PLATE	Not Necessary	74.30 FN	*- FN
11	1		*REAR PANEL	Repair	573.80 FN	*- FN
12	1		*REAR BUMPER STAY LH	Not Necessary	152.40 FN	*- FN
13	1		*REAR BUMPER STAY RH	Not Necessary	152.40 FN	*- FN
14	1		*REAR BUMPER REINFORCEMENT	Repair	746.20 FN	*- FN
15	1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	168.10 FN	*- FN
16	1		*REAR BUMPER RETAINER	Necessary	27.80 FN	*27.80 FN
17	10		*CLIP REAR BUMPER @\$8.60 EACH	Necessary	86.00 FN	*86.00 FN
18	1		*REAR BUMPER FASCIA	Deformed	946.50 FN	*946.50 FN
19	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
20	1		*REAR LICENCE PLATE	Serviceable	60.00 FS	*- FS
21	1		*REAR W/SCREEN SEALANT	Not Necessary	80.00 FS	*- FS
22	1		*SENSOR-REVERSE	Shorted	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,054.00</b>	<b>1,482.20</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	1,722.80	246.44
<b>Total Parts (\$\$)</b>	<b>7,331.20</b>	<b>1,235.76</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR CHARGES TO REPAIR TRUNK FLOOR, RENEW REAR PANEL, TAIL GATE BACK DOOR AND REAR BUMPER	New	1,800.00	1,365.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,000.00	750.00
3	RENEW REVERSE SENSOR, RE-SET AND FUNCTION TEST	New	110.00	110.00
4	RENEW REAR WINDSCREEN GLASS	New	240.00	0.00
5	REMOVE AND INSTALL REVERSE CAMERA, RESET AND FUNCTION TEST	New	150.00	0.00
6	REMOVE AND INSTALL TAIL GATE BACK DOOR MECHANISM	New	80.00	0.00
7	PERFORM RUST PROOFING TO REAR PANEL	New	120.00	0.00
8	SUPPLY REAR LICENSE PLATE (NPA)	New	0.00	0.00
9	RENEW REAR WINDSCREEN GLASS SOLAR FILM	New	150.00	0.00
Gross Labour Cost (\$\$)			3,650.00	2,225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >