



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 190Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH SLIDE DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	2,299.32	-
1	RH SLIDE DOOR WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	143.40	-
1	RH SLIDE DOOR GLASS MOULDING (CONSISTENT)	NOT NECESSARY	153.50	-
1	RH REAR QUARTER PANEL (CONSISTENT)	DENTED	1,921.89	1,921.89
1	RH REAR QUARTER MUDFLAP (CONSISTENT)	NOT NECESSARY	209.44	-
1	RH REAR QUARTER AIR VENT (CONSISTENT)	NOT NECESSARY	112.35	-
1	RH TAILLAMP (CONSISTENT)	NOT NECESSARY	418.00	-
1	REAR BUMPER (CONSISTENT)	CUT	698.00	698.00
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR BUMPER UPPER COVER RH (CONSISTENT)	NOT NECESSARY	298.00	-
1	REAR BUMPER UPPER COVER RETAINER RH (CONSISTENT)	NOT NECESSARY	69.84	-
	LESS 25% DISCOUNT		-1,594.69	-654.97
			4,784.05	1,964.92
<u>SPECIAL NETT ITEMS</u>				
1	RH SLIDE DOOR GLASS SEALANT (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	SET RH SLIDE DOOR INNER BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	RH REAR QUARTER PANEL GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	RH REAR TYRE (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	SET TAILLAMP PROTECTOR (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
			650.00	70.00
<u>LABOUR</u>				
	LABOUR CHARGE TO CHECK ELECTRICAL WIRING AND TEST REAR LIGHT FUNCTIONALITY.		120.00	30.00
	LABOUR CHARGE FOR PANEL BEATING ,STRAIGHTENING ,REMOVE -REFIT AND PARTS REPLACEMENT.INCLUSIVE OF THE REPAIR OF RH SLIDE DOOR .		1,200.00	800.00
	TO SPRAY PAINT TO AFFECTED PANELS.		1,000.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING TO CHECK THE CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT RH SLIDING DOOR GLASS .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR QUARTER PANEL GLASS .		120.00	120.00
	LABOUR CHARGE TO CONDUCT WATER LEAKAGE TEST.		80.00	30.00
			2,760.00	1,380.00
GRAND TOTAL			8,194.05	3,414.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CC4/ASM22005167/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.