



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22005167/Eea3q2 Date: 14/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7488M	Veh. Inspected	GBL 190Y
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M03W61	Excess (\$)	0.00
	Assign From		Assign Date	31/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GDH2012016643	Colour	WHITE
	Odometer	37722 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	DUNLOP	4 mm
	L/H Front Tyre	195 R15C	DUNLOP	4 mm
	R/H Rear Tyre	195 R15C	DUNLOP	4 mm
	L/H Rear Tyre	195 R15C	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/01/2022	Inspection Date	31/05/2022
	Survey held at	SKYLINK ENGINEERING PTE LTD 48 TOH GUAN ROAD EAST, #01-118, ENTERPRISE HUB, SINGAPORE 608586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days