



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 7038L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED (SN)	DENTED	1,368.71	1,368.71
4	SENSOR PRIMED @\$190.18 (SN)	NOT NECESSARY	760.72	-
4	SEAL RING SATIN BLACK @\$1.46 (SN)	NECESSARY	5.84	5.84
1	SENSOR BRACKET (SN)	NECESSARY	18.09	18.09
2	SENSOR BRACKET @\$18.09 (SN)	NECESSARY	36.18	36.18
1	SENSOR BRACKET (SN)	NECESSARY	18.09	18.09
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	85.94	85.94
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	68.85	68.85
1	SPOILER (SN)	NOT NECESSARY	507.74	-
1	FOAM INSERT (SN)	NOT NECESSARY	56.00	-
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	732.39	-
1	GUIDE PIECE LHR BUMPER BRACKET (SN)	NOT NECESSARY	102.62	-
1	GUIDE PIECE RHR BUMPER BRACKET (SN)	NOT NECESSARY	102.62	-
			3,863.79	1,601.70
	<u>LABOUR</u>			
	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR.		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR.		2,520.00	840.00
	SPRAY PAINTING.		2,400.00	800.00
			5,680.00	2,400.00
	GRAND TOTAL		9,543.79	4,001.70
RECOMMENDED COST OF REPAIRS				4,001.70

Report Ref No. CS/AIS22005169/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.