

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22005170/Vvcm4 8 SHENTON WAY #24-01 AXA TOWER Date: 22/08/2022 SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 8510S** Veh. Inspected **SMJ 568Y** Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M042O2 Excess (\$) 0.00 ONG KIAN THENG DERICK 31/05/2022 Assign From Assign Date **Vehicle Particulars & Condition** 2. KIA CERATO 1.6 Make & Model 1591 c.c HIDDEN 2019 Year of Reg. Engine No. KNAF3416MK5024729 **BLACK** Chassis No. Colour Odometer 15904 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/55 R16 NEXEN 7 mm L/H Front Tyre 205/55 R16 **NEXEN** 7 mm 205/55 R16 NEXEN R/H Rear Tyre 7 mm L/H Rear Tyre NEXEN 7 mm 205/55 R16 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 25/05/2022 Inspect Date / Time 02/06/2022 (12:00 PM) Accident Date JASON AUTOCARE PTE LTD Survey held at 2 KAKI BUKIT AVENUE 2 #02-04 KAKI BUKIT AUTOHUB SINGAPORE 417921

Report Ref No. CS3/ASM22005170/Vvcm4

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Inspected By

5a.

5b.

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

The

Remarks

Estimate Days of Repair

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE

ESTIMATED NORMAL PERIOD FOR REPAIR:

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days