

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/III22005173/ANY3E2

**Date:** 12/07/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0002072\_01

**Claimant Vehicle No :** SMD5744D **Insured Vehicle No :** PC6630L

Date of Loss: 27/05/2022 Nature of Claim: TP Claim No: MCV2022D003196

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD5744D**  
Make & Model: BMW 216I, 1.5 (A) Engine No: 34085277B38A15A  
Reg. Date: 28/08/2018 (Man. Year: 2018) Chassis No: WBA2D920705L53320  
Colour: Black Odometer: 71941 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,973.70	3,740.70	2,233.00	37.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	760.00	790.00	50.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,523.70</b>	<b>4,500.70</b>	<b>3,023.00</b>	<b>40.18</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,600.00</b>		
<b>(\$\$)</b>	7,523.70	3,600.00	3,923.70	52.15
<b>+ GST 7.00/7.00% (\$\$)</b>	526.66	252.00	274.66	52.15
<b>Nett Amount (\$\$)</b>	<b>8,050.36</b>	<b>3,852.00</b>	<b>4,198.36</b>	<b>52.15</b>

### INSPECTION

Date of Assignment: 31/05/2022

Date Inspected: 01/06/2022 Inspected At:

Mirage Motorwerkz Pte Ltd  
10 Kaki Bukit Road 2 #01-29  
First East Centre  
Singapore 417868

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2022)
Parts:	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD5744D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	985.00 FL	*985.00 FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Not Necessary	85.00 FL	*- FL
3	1		*FRONT BUMPER SENSOR RH	Damaged	260.00 FL	*260.00 FL
4	4		*FRONT BUMPER SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
5	1		*FRONT BUMPER LOGO	Necessary	78.00 FL	*78.00 FL
6	1		*HEADLAMP RH	Cracked	2,405.00 FL	*2,405.00 FL
7	1		*FRONT RH LOWER ARM	Not Necessary	388.00 FL	*- FL
8	1		*FRONT RH KNUCKLE ARM	Not Necessary	589.00 FL	*- FL
9	1		*FRONT RH SHOCK ABSORBER	Not Necessary	308.00 FL	*- FL
10	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	295.00 FL	*295.00 FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT RH WHEEL RIM	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,523.00	4,153.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	549.30	412.30
Total Parts (\$\$)	5,973.70	3,740.70

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	500.00	250.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE FRONT UNDERCARRIAGE	New	350.00	100.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,550.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >