

ASS. REC. BY:

REF:

SMO/22005176/kg

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

/ Est not ready

17/6/22 @ 3:40pm Car body (Red 84112.58, 53%)

22/6/22 @ 3:44pm revised to Ruth Chis by email.

Veh No:

GIBL 600614

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

c.c. 1861

Colour:

Gray

A/C: Insured / Std / NI / NA

Sp. Reading

113608

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VSKYRAM 2080172543

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

8

mm

L/Bal.

2

mm

L/Bal.

8

mm

D.O.A.

23/5/2

D.O.I.

7/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

F. P. OS

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

3700

TOTAL

Trust Autoworks

Trading address: Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
Tel: 91082728

Trust Maintenance Services Pte Ltd
Fax: 9140806A
100 Ang Mo Kio Ave 4
Singapore 438838

Vehicle No: GBL 6006 H
Make/Model: Nissan NV200
Year: 2018

*Not Notified
11pm @ 3700h
Repairing After Rain
6 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

pc	Front n/s fender	
pc	Front n/s door	
pc	Front n/s door view mirror	
pc	Front n/s door glass	485.10
pc	Rear n/s sliding door	
pc	Rear n/s sliding door railing	
pc	Rear n/s fender	
pc	Rear n/s tail-lamp	

R	450.70	X
R	985.70	✓
R	285.70	✓
GLT	525.60	✓
R	1075.10	✓
Rd	185.20	✓
R	1250.70	X
R	3277.50	X
	55,036.20	
	Less 10 %	
	5503.62	
	55,532.58	

pc	Front n/s door company sticker
pc	Body sticker

NEC \$30.00 ✓
NEC \$550.00 250/

Hour Charges

move/renew the above parts including knocking, welding etc

putty and spray paint

check & reconnect wiring

respray anti-rust proofing treatment

move/refit roof lining to facilitate repair

\$1,000.00 700
\$1,400.00 800
\$30.00 200
\$120.00 600
\$150.00 500
Total \$7,812.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: