



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 6006H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	450.70	-
1	FRONT N/S DOOR	BENT	985.70	985.70
1	FRONT N/S DOOR VIEW MIRROR	BROKEN	285.70	285.70
1	FRONT N/S DOOR GLASS	CUT	525.60	485.10
1	REAR N/S SLIDING DOOR	BENT	1,075.10	1,075.10
1	REAR N/S SLIDING DOOR RAILING	DENTED	185.20	185.20
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	1,250.70	-
1	REAR N/S TAIL-LAMP	SERVICEABLE	277.50	-
	LESS 10% DISCOUNT		-503.62	-301.68
			4,532.58	2,715.12
<u>SPECIAL NETT ITEMS</u>				
1	FRONT N/S DOOR COMPANY STICKER (SN)	NECESSARY	30.00	30.00
1	BODY STICKER (SN)	NECESSARY	550.00	250.00
			580.00	280.00
<u>LABOUR</u>				
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING ETC. INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER AND REAR N/S FENDER.		1,000.00	700.00
	TO PUTTY AND SPRAY PAINT.		1,400.00	800.00
	CHECK & RECONNECT WIRING.		30.00	20.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.		120.00	60.00
	REMOVE / REFIT ROOF LINING TO FACILITATE REPAIR.		150.00	50.00
			2,700.00	1,630.00
GRAND TOTAL			7,812.58	4,625.12



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	-----------------

Report Ref No. CS/SMO22005176/Kqy3e2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.