

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--|-----------------|-----------------------|--|
| | MS FIRST CAPITA | L INSURANCE LTD | Ref: | CS/FCI22005179/Dny3m4 | |
| | 36 ROBINSON RO #16-01 CITY HOUS | AD SESINGAPORE 068877 | Date: | 01/11/2022 | |
| | | | Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | PC 2449X | Veh. Inspected | SHC 7202C | |
| | Policy No. | D-21098068MFBP/18 | Coverage (\$) | 0.00 | |
| | Claim No. | D22001639MFBP | Excess (\$) | 0.00 | |
| | Assign From | AINI BINTE | Assign Date | 31/05/2022 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HYUNDAI I40 | c.c | 1685 | |
| | Engine No. | HIDDEN | Year of Reg. | 2016 | |
| | Chassis No. | KMHLB41UMGU092412 | Colour | YELLOW | |
| | Odometer | 757429 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 205/60 R16 | WEST LAKE | 5 mm | |
| | L/H Front Tyre | 205/60 R16 | WEST LAKE | 5 mm | |
| | R/H Rear Tyre | 205/60 R16 | WEST LAKE | 5 mm | |
| | L/H Rear Tyre | 205/60 R16 | WEST LAKE | 5 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 28/05/2022 | Inspection Date | 31/05/2022 | |
| | Survey held at | BLK 9 SECTOR C #01-42, SIN MING INDUSTRIAL ESTATE | | | |
| | Repairer | BIFROST AUTO PTE LTD | | | |
| 5a. | Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORI | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days | | | |
| | | | | | |