

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005180/KNY3Q2**Date:** 30/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00129732100

Claimant Vehicle No : SMQ3051P **Insured Vehicle No :** SMZ8725Z

Date of Loss: 26/05/2022 Nature of Claim: TP Claim No: SNM22D203753/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ3051P**

Make & Model: TOYOTA VOXY HYBRID, 1.8 V CVT (A) Engine No: 2ZR0D76675

Reg. Date: 07/11/2019 (Man. Year: 2019) Chassis No: ZWR800390126

Colour: Metallic Black Odometer: 179899 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 4 mm Rear Left Side: Sailun 4 mm

Front Right Side: Sailun 4 mm Rear Right Side: Sailun 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,401.10	4,649.07	11,752.03	71.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	1,790.00	2,590.00	59.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,781.10	6,439.07	14,342.03	69.01
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	20,781.10	5,100.00	15,681.10	75.46

INSPECTION

Date of Assignment: 31/05/2022

Date Inspected: 01/06/2022 Inspected At: Heng Yap Seng Auto Services - (sin Ming Drive) (HQ)
BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2022)**Parts:** M1-MPV TOYOTA VOXY HYBRID 1.8 V CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMQ3051P)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	891.60 F	*798.20 FL
2	1		*REAR BUMPER RETAINERS	N/S Distorted	95.60 F	*47.80 FL
3	2		*REAR BUMPER BRACKETS	Repair	98.90 F	*- FL
4	2		*REAR BUMPER REFLECTORS	Serviceable	92.90 F	*- FL
5	2		*REAR BUMPER TOW COVER	Dented	48.90 F	*48.90 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
7	1		*REAR TAILGATE	Bent	1,561.90 F	*1,561.90 FL
8	1		*REAR TAILGATE CENTRE LOGO	Serviceable	68.90 F	*- FL
9	1		*REAR TAILGATE OUTER CHROME HANDLE	Serviceable	769.50 F	*- FL
10	1		*REAR TAILGATE LOCK	Dented	771.80 F	*581.90 FL
11	2		*REAR TAILGATE HINGES	Repair	129.60 F	*- FL
12	2		*REAR TAILGATE DAMPERS	Serviceable	419.50 F	*- FL
13	1		*REAR TAILGATE WEATHERSTRIP(50%) (\$371.85)	Dented / Distorted	471.60 FS	*185.92 FS
14	1		*REAR TAILGATE NUMBER PLATE LAMP	Serviceable	98.70 F	*- FL
15	1		*REAR TAILGATE INNER TOP GARNISH	Serviceable	652.90 F	*- FL
16	2		*REAR TAILGATE INNER SIDE GARNISHS	Serviceable	783.60 F	*- FL
17	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	619.60 F	*- FL
18	2		*TAIL LAMPS	Serviceable	1,973.80 F	*- FL
19	1		*REAR FENDER INNER SIDE TRIMS	N/S Buckled	1,979.80 F	*681.10 FL
20	1		*REAR END PANEL	Bent	918.00 F	*781.90 FL
21	1		*REAR END PANEL TOP GARNISH	Buckled	352.90 F	*204.50 FL
22	1		*REAR SPARE TYRE COMPARTMENT	Repair	1,211.90 F	*- FL
23	1		*REAR SPARE TYRE TOP BOARD	Cracked	938.00 F	*938.00 FL
24	1		*REAR EXHAUST SILENCER	Repair	711.60 F	*- FL
25	1		*REAR EXHAUST SILENCER MOUNTING	Serviceable	89.60 F	*- FL
26	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
27	1		*SET REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
28	1		*REVERSE CAMERA	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,401.10	6,070.12
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,421.05
Total Parts (\$)	16,401.10	4,649.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CUT OUT DAMAGE PORTION ,JACK OUT ,STRAIGHTEN ,PANEL BEATING ,WELDING ,ALIGN AND RENEW REPLACED PARTS	New	1,800.00	700.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	800.00
3	TO REMOVE,REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	New	300.00	60.00
4	TO REMOVE,REPLACE REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO REMOVE,REPLACE REVERSE CAMERA	New	150.00	40.00
6	TO REMOVE,REPLACE REVERSE SENSOR	New	150.00	50.00
7	TO REMOVE,REPLACE REAR EXHAUST SILENCER	New	200.00	0.00
8	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (\$)			4,380.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >