



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 2521L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BRAKE LEVER (RHS)	CUT	28.00	28.00
1	FRONT FENDER	CRACKED	250.00	250.00
1	FORK ASSEMBLY	BENT	580.00	580.00
1	STEERING CONE	NECESSARY	140.00	140.00
1	HORN COVER	CUT	65.00	65.00
1	MIRROR (LHS)	CUT	70.00	70.00
1	SET BEADING	CRACKED	250.00	250.00
1	HEAD LAMP ASSEMBLY (LED)	CRACKED	350.00	350.00
1	TOP BOX ASSY	CRACKED	480.00	480.00
1	FRONT COMPARTMENT	CRACKED	220.00	220.00
	LESS 10% DISCOUNT		-	-243.30
			2,433.00	2,189.70
	<u>SPECIAL NETT ITEMS</u>			
1	IU BRACKET (SN)	BROKEN	20.00	20.00
1	RIM REPAIR (SN)	BENT	90.00	90.00
1	NUMBER PLATE FRONT STICKER TYPE (SN)	NECESSARY	15.00	15.00
			125.00	125.00
	<u>LABOUR</u>			
	BODY REPAIR.		450.00	300.00
	PAINT WORK.		900.00	500.00
	LABOUR CHARGES.		250.00	150.00
	TOWING SERVICE.		50.00	50.00
			1,650.00	1,000.00
	GRAND TOTAL		4,208.00	3,314.70
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			3,314.70

Report Ref No. CS/INC22005184/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.