



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SBS 5120E

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	WHEELARCH TRIM;N/S&O/S	CUT	41.00
1	SIDE PANEL JR~KR.O/S.SIDE PANEL ASSY	BENT	244.00
1	SIDE PANEL.O/S&N/S.ALUM	BENT	79.00
1	STKR SBS TRANSIT OS/NS.SG BUS	NECESSARY	8.00
1	SIDE PANEL GR~HR.O/S.2.5MM ALUM	BENT	95.00
1	SIDE PANEL ER~GR.O/S.2.5MM.A/B/C SER8ES	BENT	385.00
1	FLAP DOOR FL~GL+FR~GR;0.25X0.3M	BENT	79.00
			931.00
	<b><u>LABOUR</u></b>		
	CONTRACTOR LABOUR COST.		850.00
	WORKSHOP LABOUR COST.		188.00
	ADVERTISEMENT COST. (NPA)	NOT NECESSARY	-
	TOW COST. (NPA)	NOT NECESSARY	-
			1,038.00
<b>GRAND TOTAL</b>			<b>1,969.00</b>

<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>	<b>1,969.00</b>
---	-----------------

Report Ref No. CS/INC22005186/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.