

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 25K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (WCP)	DENTED	1,800.00	1,800.00
1	BONNET LOGO (WCP)	NOT NECESSARY	85.00	-
1	BONNET INSULATION (WCP)	SERVICEABLE	250.00	-
10	BONNET INSULATION CLIPS (WCP)	NOT NECESSARY	30.00	-
1	FRONT RHS FENDER (WCP)	DENTED	850.00	850.00
1	FRONT BUMPER (WCP)	CUT	1,550.00	1,550.00
10	FRONT BUMPER CLIPS (WCP)	NECESSARY	36.00	36.00
1	FRONT BUMPER RETAINER RHS (WCP)	NECESSARY	65.00	65.00
2	FRONT RHS SPLASH SHIELD (WCP)	SERVICEABLE	320.00	-
10	FRONT RHS SPLASH SHIELD CLIPS (WCP)	NOT NECESSARY	30.00	-
1	RHS HEADLAMP (WCP)	CRACKED	3,500.00	3,500.00
1	RHS HEADLAMP LOWER BRACKET (WCP)	SERVICEABLE	180.00	-
	COST PLUS 10%		869.60	780.10
			9,565.60	8,581.10
	SPECIAL NETT ITEMS			
1	SET FRONT NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	SET FRONT BUMPER SENSORS (SN)	SERVICEABLE	1,320.00	-
1	SET FRONT BUMPER SENSORS BRACKET (SN)	SERVICEABLE	120.00	-
			1,500.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE & INSTALL RHS FRONT ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.		1,800.00	600.00
	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT RHS FENDER, RHS "A" PILLAR.		1,500.00	600.00
	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.		280.00	60.00
	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.		200.00	30.00
			3,780.00	1,290.00
	GRAND TOTAL		14,845.60	9,871.10

Report Ref No. CS6/AIS22005194/Vqy3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		9,871.10
LESS EXCESS		-600.00
NETT LIABILITY		9,271.10

Report Ref No. CS6/AIS22005194/Vqy3m4



THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser