

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005206/EVY3M4**Date:** 28/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00071072203
Claimant Vehicle No :	SMA6783A	Insured Vehicle No :	SMF4445M
Date of Loss:	29/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203786/C02/KAHLEONG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6783A	Engine No:	2ZR0B83934
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDZS3EU10J028074
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	328440 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,903.25	8,106.05	11,797.20	59.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,142.20	8,506.00	6,636.20	43.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	35,045.45	16,612.05	18,433.40	52.60
+ GST 7.00/7.00% (\$\$)	2,453.18	1,162.84	1,290.34	52.60
Nett Amount (\$\$)	37,498.63	17,774.89	19,723.74	52.60

INSPECTION

Date of Assignment:	01/06/2022		
Date Inspected:	01/06/2022	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	11.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6783A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILLE SUB-ASSY,	Broken	597.00 FS	*597.00 FS
2	1		*COVER, FR BUMPER	Crushed	25.80 FS	*25.80 FS
3	1		*SEAL, FR BUMPER	Necessary	28.60 FS	*28.60 FS
4	1		*ABSORBER, FR BUMPER	Not Necessary	84.20 FS	*- FS
5	1		*SEAL, HOOD TO FR END	Not Necessary	108.50 FS	*- FS
6	1		*COVER, FR BUMPER	Broken	589.50 FS	*589.50 FS
7	1		*GRILLE, RADIATOR	Not Necessary	510.10 FS	*- FS
8	1		*UNIT ASSY, HEADLAMP,	Not Necessary	2,678.10 FS	*- FS
9	1		*UNIT ASSY, HEADLAMP,	Not Necessary	2,678.10 FS	*- FS
10	1		*EMBLEM ASSY,	Not Necessary	112.30 FS	*- FS
11	1		*PLATE, LUGGAGE COMPT	Necessary	58.00 FS	*58.00 FS
12	1		*PLATE, BACK DOOR	Necessary	67.20 FS	*67.20 FS
13	1		*ARM SUB-ASSY, RR	Not Necessary	186.30 FS	*- FS
14	1		*ARM SUB-ASSY, RR	Not Necessary	186.30 FS	*- FS
15	1		*REINFORCEMENT	Dented	230.20 FS	*230.20 FS
16	1		*COVER, RR BUMPER	Broken	589.50 FS	*589.50 FS
17	1		*SUPPORT, RR BUMPER	Broken	151.20 FS	*151.20 FS
18	1		*SUPPORT, RR BUMPER	Not Necessary	151.20 FS	*- FS
19	1		*RETAINER, RR BUMPER	Broken	62.70 FS	*62.70 FS
20	1		*RETAINER, RR BUMPER	Not Necessary	62.70 FS	*- FS
21	10		*PIECE, RR BUMPER	Necessary	43.00 FS	*43.00 FS
22	1		*SPOILER, RR NO.1	Broken	899.70 FS	*899.70 FS
23	1		*PANEL SUB-ASSY, BODY	Dented	738.00 FS	*738.00 FS
24	1		*PAN, RR FLOOR	Not Necessary	739.90 FS	*- FS
25	1		*PLATE, BACK DOOR	Not Necessary	192.50 FS	*- FS
26	1		*BOARD ASSY, DECK	Not Necessary	575.40 FS	*- FS
27	1		*GLASS SUB-ASSY, BACK	Necessary	1,093.60 FS	*1,093.60 FS
28	1		*DAM, WINDOW GLASS	Necessary	30.60 FS	*30.60 FS
29	1		*WEATHERSTRIP, BACK	Not Necessary	355.10 FS	*- FS
30	1		*PANEL SUB-ASSY, BACK (TAILGATE)	Dented	1,177.30 FS	*1,177.30 FS
31	1		*BOARD ASSY, BACK	Not Necessary	348.70 FS	*- FS
32	1		*LOCK ASSY, BACK DOOR	Not Necessary	437.70 FS	*- FS
33	1		*LENS & BODY, RR	Not Necessary	730.90 FS	*- FS
34	1		*LENS & BODY, RR	Not Necessary	706.10 FS	*- FS
35	1		*PIPE ASSY, EXHAUST	Not Necessary	798.70 FS	*- FS
36	2		*SUPPORT, EXHAUST	Not Necessary	104.40 FS	*- FS
37	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	216.00 FS	*216.00 FS
38	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
39	1		*BACK SENSOR BLACK AGEHA	Broken	101.05 FS	*101.05 FS
40	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
41	1		*ANTENNA, ELECTRICAL	Broken	203.90 FS	*203.90 FS
42	1		*ARM SUB-ASSY, RR	Bent	186.30 FS	*186.30 FS
43	1		*ARM SUB-ASSY, RR	Bent	186.30 FS	*186.30 FS
44	1		*COVER SUB-ASSY, RR	Crushed	580.60 FS	*580.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	19,903.25	8,106.05
--------------------	-----------	----------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP	New	180.00	0.00
2	REPL ACC AFF PARTS AND PANEL FRT PORTION	New	1,440.00	720.00
3	RESPRAY ACC AFF AREA FRT PORTION	New	1,180.00	590.00
4	SUPPLY REGN PLATE (PO#) FRT	New	80.00	80.00
5	CONDUCT LEAK TEST REAR PORTION	New	180.00	180.00
6	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
7	TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA	New	540.00	540.00
8	REPL REAR WINDSCREEN	New	466.20	462.00
9	SUPPLY PHV STICKER	New	20.00	20.00
10	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
11	R/I INTERIOR UPHOLSTERY TO FAC REPAIR	New	616.00	0.00
12	SUPPLY SEALANT (NETT) 3 PANEL	New	240.00	160.00
13	REPLACE ACC AFF PARTS AND PANEL REAR PORTION	New	5,760.00	2,880.00
14	RESPRAY ACC AFF AREA REAR PORTION	New	3,540.00	2,360.00
15	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	154.00
16	REPLACE REAR EXHAUST ASSY	New	360.00	0.00
Gross Labour Cost (\$\$)			15,142.20	8,506.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >