

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22005207/KVY3E2

Date: 23/08/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SKU7879U **Insured Vehicle No :** SJU9707G
Date of Loss: 28/05/2022 Nature of Claim: TP Claim No: DMPC2200220H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU7879U**
Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB7103424
Reg. Date: 13/03/2019 (Man. Year: 2018) Chassis No: GP72002599
Colour: Metallic Pearl White Odometer: 27295 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,746.92	2,212.64	1,534.28	40.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,115.00	825.00	42.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,686.92	3,327.64	2,359.28	41.49
+ GST 7.00/7.00% (S\$)	398.08	232.93	165.15	41.49
Nett Amount (S\$)	6,085.00	3,560.57	2,524.43	41.49

INSPECTION

Date of Assignment: 01/06/2022
Date Inspected: 02/06/2022 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Aug 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU7879U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MLDG	Necessary	149.20 FL	*149.20 FL
2	1		*TAILGATE	Bent	1,193.20 FL	*1,193.20 FL
3	1		*TAILGATE SHUTTLE LOGO	Necessary	89.40 FL	*89.40 FL
4	1		*TAILGATE HYBRID LOGO	Necessary	80.10 FL	*80.10 FL
5	1		*TAILGATE INNER TRIM LOWER	Serviceable	220.70 FL	*- FL
6	1		*TAILGATE LOCK	Repair	256.90 FL	*- FL
7	1		*TAILGATE RUBBER	Serviceable	168.20 FL	*- FL
8	1		*REAR BUMPER	Buckled	1,150.90 FL	*1,150.90 FL
9	1		*REAR BUMPER REFLECTOR LH	Serviceable	54.70 FL	*- FL
10	1		*REAR BUMPER REFLECTOR COVER LH	Serviceable	45.20 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	24.30 FL	*- FL
12	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
13	1		*REAR END PANEL	Repair	560.40 FL	*- FL
14	1		*REAR END PANEL GARNISH	Serviceable	155.50 FL	*- FL
15	1		*REAR KEYLESS ANTENNA	Serviceable	58.10 FL	*- FL
16	1		*REAR BUZZER	Serviceable	80.10 FL	*- FL
17	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
18	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
19	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
20	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,609.90	2,750.80
- List Item Discount on L Items 20.00/20.00% (S\$)	862.98	538.16
Total Parts (S\$)	3,746.92	2,212.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL / REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
4	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS	New	60.00	50.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
7	TO SPRAY TAILGATE, REAR BUMPER, RR END PANEL, SPARE TYRE PANEL	New	800.00	440.00
Gross Labour Cost (\$\$)			1,940.00	1,115.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >