

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22005208/KVY3Q2**Date:** 27/10/2022**REFERENCE**

Insured/Claimant: LEE KONG HOCK Policy No: DMPCSNW00059882200

Date of Loss: 27/05/2022 Nature of Claim: OD Claim No: SNM22D203804/C01/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGT7769G**

Make &amp; Model: MERCEDES-BENZ 200E, 2.0 (A)

Engine No: 65492080916651

Reg. Date: 05/03/2021 (Man. Year: 2020)

Chassis No: W1K2130042A876588

Colour: Black

Odometer: 64776 km

Engine Capacity: 1950 cc

Market Value/New Car Price: S\$227,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/40 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 21,845.00         | 12,314.00         | 9,531.00          | 43.63         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 4,200.00          | 1,530.00          | 2,670.00          | 63.57         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>26,045.00</b>  | <b>13,844.00</b>  | <b>12,201.00</b>  | <b>46.85</b>  |
| <b>- Excess (S\$)</b>               | 500.00            | 500.00            | 0.00              | 0.00          |
| <b>(S\$)</b>                        | 25,545.00         | 13,344.00         | 12,201.00         | 47.76         |
| <b>+ GST 7.00/7.00% (S\$)</b>       | 1,788.15          | 934.08            | 854.07            | 47.76         |
| <b>Nett Amount (S\$)</b>            | <b>27,333.15</b>  | <b>14,278.08</b>  | <b>13,055.07</b>  | <b>47.76</b>  |

**INSPECTION**

Date of Assignment: 01/06/2022

Date Inspected: 01/06/2022 Inspected At:

160 Sin Ming Drive #07-17 Autocity

Singapore 575722

Repairer:Cartimes Autolution (HQ)

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 27 Oct 2022)                |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MERCEDES-BENZ 200E 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                            |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGT7769G)                                                                                                                                    |                                                              |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                              |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                              |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                          | Condition   | Repairer's | Amount      |
|-----|-----|----------|------------------------------------------------------|-------------|------------|-------------|
| 1   | 1   |          | <b>*FRONT BUMPER</b><br>(WCP)                        | Cracked     | 1,100.00 F | *790.00 F   |
| 2   | 1   |          | <b>*FRONT BUMPER RETAINER RHS</b><br>(WCP)           | Distorted   | 100.00 F   | *50.00 F    |
| 3   | 1   |          | <b>*FRONT BUMPER TOWING COVER</b><br>(WCP)           | Missing     | 80.00 F    | *95.00 F    |
| 4   | 1   |          | <b>*FOG LAMP COVER RHS</b><br>(WCP)                  | Missing     | 100.00 F   | *70.00 F    |
| 5   | 1   |          | <b>*FRONT BUMPER CHROME GARNISH RHS</b><br>(WCP)     | Missing     | 150.00 F   | *105.00 F   |
| 6   | 1   |          | <b>*HEADLAMP RHS</b><br>(WCP)                        | Broken      | 4,000.00 F | *2,400.00 F |
| 7   | 1   |          | <b>*FRONT FENDER RHS</b><br>(WCP)                    | Bent        | 1,600.00 F | *560.00 F   |
| 8   | 1   |          | <b>*FRONT FENDER INNER SHIELD RHS</b><br>(WCP)       | Cracked     | 430.00 F   | *225.00 F   |
| 9   | 1   |          | <b>*FRONT BONNET</b><br>(WCP)                        | Bent        | 2,600.00 F | *1,650.00 F |
| 10  | 1   |          | <b>*FRONT LOWER ARM RHS</b><br>(WCP)                 | Distorted   | 600.00 F   | *380.00 F   |
| 11  | 1   |          | <b>*FRONT STEERING KNUCKLE RHS</b><br>(WCP)          | Bent        | 2,100.00 F | *1,250.00 F |
| 12  | 1   |          | <b>*FRONT ABSORBER RHS</b><br>(WCP)                  | Bent        | 890.00 F   | *540.00 F   |
| 13  | 1   |          | <b>*FRONT WHEELHUB W/BEARING RHS</b><br>(WCP)        | Necessary   | 630.00 F   | *380.00 F   |
| 14  | 1   |          | <b>*FRONT REINFORCEMENT</b><br>(WCP)                 | Repair      | 2,400.00 F | *- F        |
| 15  | 1   |          | <b>*WIPER RESERVOIR</b><br>(WCP)                     | Serviceable | 200.00 F   | *- F        |
| 16  | 1   |          | <b>*FRONT SENSORS RHS</b><br>(WCP)                   | Missing     | 270.00 F   | *230.00 F   |
| 17  | 1   |          | <b>*SET FRONT BUMPER CLIPS</b>                       | Necessary   | 60.00 FS   | *60.00 FS   |
| 18  | 1   |          | <b>*FRONT CARPLATE</b>                               | Serviceable | 60.00 FS   | *- FS       |
| 19  | 1   |          | <b>*FRONT UPPER ARM RHS</b><br>(WCP)                 | Distorted   | 520.00 F   | *520.00 F   |
| 20  | 1   |          | <b>*TIE ROD RHS</b><br>(WCP)                         | Bent        | 150.00 F   | *150.00 F   |
| 21  | 1   |          | <b>*TIE ROD END RHS</b><br>(WCP)                     | Bent        | 210.00 F   | *210.00 F   |
| 22  | 1   |          | <b>*FRONT REINFORCEMENT TOP BRACKET RHS</b><br>(WCP) | Distorted   | 60.00 F    | *60.00 F    |
| 23  | 1   |          | <b>*FRONT REINFORCEMENT SPONGE</b><br>(WCP)          | Cracked     | 140.00 F   | *140.00 F   |
| 24  | 1   |          | <b>*FRONT BUMPER INNER GARNISH RHS</b><br>(WCP)      | Cracked     | 60.00 F    | *60.00 F    |
| 25  | 1   |          | <b>*FRONT BUMPER INNER LOWER GARNISH</b><br>(WCP)    | Cracked     | 80.00 F    | *80.00 F    |
| 26  | 1   |          | <b>*FRONT BUMPER LOWER CHROME GARNISH</b><br>(WCP)   | Dented      | 150.00 F   | *120.00 F   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                           | Condition | Repairer's                                     | Amount                          |
|-----|-----|----------|---------------------------------------|-----------|------------------------------------------------|---------------------------------|
| 27  | 1   |          | *FRONT GRILLE CHROME GARNISH<br>(WCP) | Cracked   | 320.00 F                                       | *320.00 F                       |
| 28  | 1   |          | *FRONT CONTROL ARM RHS<br>(WCP)       | Bent      | 690.00 F                                       | *690.00 F                       |
| 29  | 1   |          | *ANTI ROLL BAR LINKAGE RHS<br>(WCP)   | Distorted | 120.00 F                                       | *65.00 F                        |
|     |     |          |                                       |           |                                                |                                 |
|     |     |          |                                       |           | <b>Sub Total (\$)</b>                          | <b>19,870.00      11,200.00</b> |
|     |     |          |                                       |           | <b>+ Margin on L,N Items 10.00/10.00% (\$)</b> | <b>1,975.00      1,114.00</b>   |
|     |     |          |                                       |           | <b>Total Parts (\$)</b>                        | <b>21,845.00      12,314.00</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                          | Lab.Type | Repairer's      | Amount          |
|--------------------------------|------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                      |          |                 |                 |
| 1                              | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS    | New      | 1,800.00        | 500.00          |
| 2                              | TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED & REPAIRED        | New      | 1,800.00        | 750.00          |
| 3                              | TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS | New      | 100.00          | 20.00           |
| 4                              | TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS                                                     | New      | 100.00          | 0.00            |
| 5                              | DIGNOSTIC CHECK                                                                                      | New      | 100.00          | 0.00            |
| 6                              | ALIGNMENT CHECK                                                                                      | New      | 100.00          | 80.00           |
| 7                              | REMOVE & REFIT FRONT RIGHT UNDER CARRIAGE                                                            | New      | 200.00          | 180.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                      |          | <b>4,200.00</b> | <b>1,530.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >