



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6933T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	BUCKLED / CRACKED	320.00	320.00
1	FRONT BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	205.00	-
1	FRONT BUMPER REINFORCEMENT OUTER PANEL (WCP)	TO REPAIR SEE LABOUR	98.00	-
1	HEADLAMP RH (WCP)	SERVICEABLE	1,200.00	-
	COST PLUS 15%		273.45	48.00
			2,096.45	368.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	35.00	35.00
			35.00	35.00
	<u>LABOUR</u>			
	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, GRILLE, TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT BUMPER REINFORCEMENT OUTER PANEL.		480.00	250.00
	PUTTY & RESPRAY ON FRT BUMPER, GRILLE, REINFORCEMENT.		550.00	350.00
			1,030.00	600.00
GRAND TOTAL			3,161.45	1,003.00
RECOMMENDED COST OF REPAIRS				1,003.00

Report Ref No. CS/GAI22005210/Kcy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.