

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22005212/Etcm4	
	8 SHENTON WAY SINGAPORE 0688		Date:	06/06/2022		
	ATTN: ANG YVONI	NE		Code:	ASM	
1.	I. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMF 6986E	Veh. Inspected	H	FBH 4232E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M041SU	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		01/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA R15	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	ME11CK044D2006573	Colour		WHITE	
	Odometer	103090 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	80/90-17	BRIDGESTONE		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/90-17	BRIDGESTONE		4 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.					
5.	5. General Information					
	Accident Date	19/05/2022	Inspect Date /	Time	01/06/2022 (03:52 PM)	
	Survey held at	RWAVE PTE LTD				
		50 BUKIT BATOK STREET 23 #02-25 MIDVIEW BUILDING SINGAPORE 659578				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22005212/Etcm4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser