

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 20T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP RH	CUT	2,549.00	2,549.00
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	187.00	-
1	FRONT BUMPER	BROKEN	1,446.00	1,446.00
1	FRONT BUMPER LOWER	CUT	354.00	354.00
1	FRONT PARKING SENSOR OUTER RH	NOT NECESSARY	295.00	-
1	FRONT BUMPER SIDE RETAINER RH	BROKEN	36.00	36.00
10	FRONT BUMPER CLIPS @\$5.00	NOT NECESSARY	50.00	-
16	RIVET @\$6.00	NOT NECESSARY	96.00	-
1	FRONT FENDER ARCH GARNISH RH	CUT	245.00	245.00
10	FRONT FENDER ARCH GARNISH CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT FENDER COWLING RH	NOT NECESSARY	145.00	-
10	FRONT FENDER COWLING CLIPS @\$5.00	NOT NECESSARY	50.00	-
1	FRONT WHEEL RIM RH - REPAIR (NPA)	NOT NECESSARY	-	-
1	FRONT FENDER RH - REPAIR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 5% DISCOUNT		-275.15	-233.00
			5,227.85	4,427.00
	SPECIAL NETT ITEMS			
1	FRONT TYRE RH (SN)	SERVICEABLE	280.00	-
			280.00	-
	<u>LABOUR</u>			
	TO INSPECT FRONT LIGHTING MECHANISM & CHECK WIRING.		80.00	50.00
	TO INSTALL PARKING SENSOR & DIAGNOSE FUNCTION.		80.00	30.00
	TO REPAIR ON FRONT FENDER RH. TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION.		500.00	300.00
	TO SPRAY PAINT ON REPAIRED AREAS.		500.00	450.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REFURNISH FRONT WHEEL RIM RH.	NOT NECESSARY	180.00	-
			1,420.00	830.00
	GRAND TOTAL		6,927.85	5,257.00

Report Ref No. CS/SMR22005213/Evy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMR22005213/Evy3m4



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator