

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005214/UPA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220048751
Claimant Vehicle No :	SME1201A	Insured Vehicle No :	SJS505S
Date of Loss:	31/05/2022	Nature of Claim:	TP
		Claim No:	3512083733SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1201A	Engine No:	L15B6021196
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82101011
Reg. Date:	25/09/2020 (Man. Year: 2019)	Odometer:	82636 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,809.60	7,527.84	9,281.76	55.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	2,560.00	1,760.00	40.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,129.60	10,087.84	11,041.76	52.26
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	21,129.60	8,000.00	13,129.60	62.14
+ GST 7.00/7.00% (S\$)	1,479.07	560.00	919.07	62.14
Nett Amount (S\$)	22,608.67	8,560.00	14,048.67	62.14
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,167.45		

INSPECTION

Date of Assignment:	01/06/2022	
Date Inspected:	01/06/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	166.20 F	*166.20 FL
2	1		*TAILGATE	Badly Dented	1,455.20 F	*1,254.20 FL
3	1		*TAILGATE REAR LOGO	Not Necessary	48.00 F	*- FL
4	2		*TAILGATE REFLECTORS	Not Necessary	683.20 F	*- FL
5	1		*TAILGATE SHUTTLE EMBLEM	Necessary	75.00 F	*72.00 FL
6	1		*TAILGATE OUTER GARNISH	Not Necessary	495.00 F	*- FL
7	1		*TAILGATE INNER LOCK	Bent	288.20 F	*265.10 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	455.10 F	*415.20 FL
9	1		*TAILGATE WEATHERSTRIP	Twisted	232.80 F	*232.80 FL
10	2		*TAILLAMPS	Cracked	1,900.00 F	*1,370.00 FL
11	1		*REAR BUMPER	Distorted	1,415.10 F	*985.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Bent	90.00 F	*90.00 FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	150.00 F	*- FL
14	2		*REAR BUMPER SIDE COVERS	Not Necessary	222.00 F	*- FL
15	1		*REAR BUMPER INNER SPONGE	Not fitted	183.00 F	*- FL
16	1		*REAR END PANEL	Badly Dented	755.20 F	*691.00 FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	248.70 F	*248.70 FL
18	1		*REAR END PANEL ANTENNA SENSOR	Cracked	108.90 F	*108.90 FL
19	2		*REAR END PANEL SIDE EXTENSION PANELS	Bent / Dented	570.00 F	*570.00 FL
20	1		*REAR EXHAUST	Not Necessary	688.20 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	544.10 F	*- FL
22	1		*REAR FLOOR PANEL	Repair	1,140.20 F	*- FL
23	1		*REAR FLOOR PANEL TOOLS TRAY	Cracked	652.30 F	*495.20 FL
24	1		*REAR BUMPER TOOLS SPONGE	Torn	588.00 F	*588.00 FL
25	2		*REAR FENDER INNER TRIM BOARDS	Deformed / Torn	1,380.00 F	*970.00 FL
26	1		*REAR FENDER	Repair	1,155.20 F	*- FL
27	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
30	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
32	1		*REAR BUMPER TOP CHROME PLATE	Bent	380.00 FS	*280.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
34	1		*SET REAR FLOOR PANEL INSULATOR	Not fitted	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,809.60	9,232.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,704.46
Total Parts (\$\$)	16,809.60	7,527.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
6	TO SPRAY RUST PROOFING	New	100.00	80.00
7	TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	New	120.00	50.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	1,000.00
9	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (S\$)			4,320.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >