8/29/22, 1:27 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22005215/KVY3Q2

29/08/2022 Date:

REFERENCE

Handling Insurer: **ECICS Limited**

Policy No:

Claimant Vehicle SHB7659Z Insured Vehicle No: SMN9538D No:

Date of Loss: 29/05/2022 Nature of Claim: Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7659Z

Make & Model: TOYOTA 86, 2.0 (A) Engine No: 2ZR2C50678

Reg. Date: 30/08/2019 (Man. Year: 2018) Chassis No: JTDKB3FU903083280

Metallic Pearl White/Red Colour: Odometer: 0 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Sailun 3 mm Rear Left Side: Firenza 8 mm Front Right Side: Sailun 3 mm Rear Right Side: Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,228.27	5,831.87	5,396.40	48.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,680.00	2,870.00	4,810.00	62.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	\$) 18,908.27	8,701.87	10,206.40	53.98
+ GST 7.00/7.00% (S	\$) 1,323.58	609.13	714.45	53.98
Nett Amount (S	\$) 20,231.85	9,311.00	10,920.85	53.98

INSPECTION

Date of Assignment: 01/06/2022

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 01/06/2022 Inspected At: Date Inspected:

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/29/22, 1:27 PM Adjuster Report

Different 1 cents -Finalise confirm amount: \$8,701.88

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Aug 2022)

Parts: M1-COUPE TOYOTA 86 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB7659Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER LOWER	Missing	15.40 FL	*15.40 FL
4	1		*GUARD ,REAR BUMPER CENTER	Bent / Cracked	576.30 FL	*576.30 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Distorted	117.70 FL	*117.70 FL
7	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Mtg Cracked	123.70 FL	*123.70 FL
8	1		*PANEL SUB-ASSY,BACK DOOR	Bent	1,147.80 FL	*1,147.80 FL
9	1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Cracked	925.60 FL	*925.60 FL
10	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
11	1		*WEATHERSTRIP ,BACK DOOR	Serviceable	372.30 FL	*- FL
12	1		*BOARD ,BACK DOOR TRIM	Serviceable	225.20 FL	*- FL
13	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH (UPPER)	Cracked	451.80 FL	*451.80 FL
14	1		*LENS AND BODY ,REAR LAMP RH (LOWER)	Cracked	502.00 FL	*502.00 FL
15	1		*BOX,DECK FLOOR RH	Serviceable	313.60 FL	*- FL
16	1		*BOX,DECK FLOOR LH	Serviceable	313.00 FL	*- FL
17	1		*BOAR ,REAR FLOOR ,NO.1	Serviceable	519.00 FL	*- FL
18	1		*BOX ,DECK ,FLOOR ,REAR	Serviceable	105.80 FL	*- FL
19	1		*PANEL ASSY ,DECK TRIM SIDE RH	Serviceable	355.90 FL	*-FL
20	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
21	1		*COVER ,FLOOR UNDER NO.2 RH	Cracked	241.90 FL	*241.90 FL
22	1		*COVER REAR FLOOR CTR	Cracked	229.90 FL	*229.90 FL
23	1		*COVER,DECK TRIM REAR	Serviceable	126.70 FL	*-FL
24	1		*PANEL SUB-ASSY BODY LOWER BACK	Bent	650.30 FL	*650.30 FL
25	1		*LOCK ASSY BACK DOOR W/COURTESY LAMP SWITCH	Repair	467.00 FL	*-FL
26	1		*SWITCH ASSY ,BACK DOOR OPENER	Serviceable	179.10 FL	*-FL
27	1		*SEAL ,REAR BUMPER SIDE RH	Serviceable	88.50 FL	*-FL
28	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
29	1		*STAY ASSY ,BACK DOOR, RH	Serviceable	242.50 FL	*- FL
30	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
31	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*-FL
32	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.90 FL	*47.90 FL
33	1		*REAR TAILGATE WORDING PRIUS	Necessary	54.60 FL	*54.60 FL
34	1		*LINER ,REAR WHEELHOUSE RH	Serviceable	139.80 FL	*-FL
35	1		*PANEL SUB-ASSY ,QUARTER RH	Repair	871.50 FL	*-FL
36	1		*REAR TAILGATE WORDING HYUBRID	Necessary	54.60 FL	*54.60 FL
37	1		*REAR SPARE TYRE PANEL	Bent	667.70 FL	*667.70 FL
38	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
39	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
40	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
41	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
42	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS
43	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
44	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
45	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
46	2		*SEAM SEALANT	Not Necessary	250.00 FS	*-FS
-1 U	_		VEAIN VEAEAN I	140t 1400essaly	200.0013	-1-0

*SET REAR BUMPER RETAINER CLIP *REAR NUMBER PLATE WITH HOLDER *SET TAILLAMP LOWER CLIP *SET TAILLAMP UPPER CLIP	Not Necessary Dented Necessary	85.00 FS 140.00 FS 55.00 FS	
*SET TAILLAMP LOWER CLIP	Necessary		*45.00 FS
	,	55.00 FS	*EE 00 EC
*SET TAILLAMP UPPER CLIP	NI		*55.00 FS
	Necessary	55.00 FS	*55.00 FS
*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
*REAR BUMPER ADVERTISEMENT STICKER	Necessary	100.00 FS	*60.00 FS
=SpcNett. L=ListItemDisc. - List Item Discount on L I	· · · /	•	7,477.50 1,645.63
	Total Parts (S\$)	11,228.27	5,831.87
:=	*REAR BUMPER ADVERTISEMENT STICKER =SpcNett. L=ListItemDisc List Item Discount on L	*REAR BUMPER ADVERTISEMENT STICKER Necessary =SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)	*REAR BUMPER ADVERTISEMENT STICKER Necessary 100.00 FS =SpcNett. L=ListItemDisc. Sub Total (\$\$) 14,182.70 - List Item Discount on L Items 25.00/25.00% (\$\$) 2,954.43 Total Parts (\$\$) 11,228.27

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	180.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	100.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	1,200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	100.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
6	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
9	TOWING FEES	New	150.00	0.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	1,100.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
13	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
14	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
	Gross Labour Cost (S\$)		7,680.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >