

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005216/RNY3E2

Date: 06/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00238872101

**Claimant Vehicle
No :** SGF53H

**Insured
Vehicle No :** SKA1812G

Date of Loss: 29/05/2022

Nature of Claim: TP

Claim
No: SNM22D203767/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF53H**

Make & Model: SKODA SUPERB, 1.8 Ambition (A)

Engine No: CHH284023

Reg. Date: 30/01/2019 (Man. Year: 2018)

Chassis No: TMBBD8NPXJ7610854

Colour: Red

Odometer: 93648 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,513.73	11,379.27	6,134.46	35.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,570.00	11,250.00	3,320.00	22.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,083.73	22,629.27	9,454.46	29.47
+ GST 7.00/7.00% (S\$)	2,245.86	1,584.05	661.81	29.47
Nett Amount (S\$)	34,329.59	24,213.32	10,116.27	29.47

INSPECTION

Date of Assignment: 01/06/2022

Date Inspected: 03/06/2022 Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 13.0 days

Adjuster: MOHD RASUL

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2022)
Parts: 143	SKODA SUPERB 1.8 Ambition (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF53H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR REAR BUMPER	Deformed	2,124.92 FS	*2,124.92 FS
2	1		*COVER FOR TOWING CAP	Cut	31.57 FS	*31.57 FS
3	1		*GUIDE PIEC LHR BUMPER BRACKET (SIDE)	Not Necessary	58.52 FS	*- FS
4	1		*GUIDE PIEC RHR BUMPER BRACKET (SIDE)	Not Necessary	58.52 FS	*- FS
5	1		*GUIDE PIEC LHR BUMPER BRACKET (UPPER)	Not Necessary	58.52 FS	*- FS
6	1		*GUIDE PIEC RHR BUMPER BRACKET (UPPER)	Not Necessary	58.52 FS	*- FS
7	1		*RETAINING RR BUMPER BRACKET (CTR)	Cracked	95.52 FS	*95.52 FS
8	1		*SENSOR BRACKET	Necessary	45.94 FS	*45.94 FS
9	1		*SENSOR BRACKET	Necessary	45.94 FS	*45.94 FS
10	1		*SENSOR BRACKET	Necessary	45.94 FS	*45.94 FS
11	1		*SENSOR BRACKET	Necessary	45.94 FS	*45.94 FS
12	1		*SEAL RING SATIN BLACK (4PCS)	Necessary (2Pcs Only)	5.84 FS	*2.92 FS
13	1		*SENSOR PRIMED (4PCS)	Distorted (2Pcs Only)	760.72 FS	*380.36 FS
14	1		*HARNES FO REAR PARKING SENSOR WIRE HOUSING	Not Necessary	81.55 FS	*- FS
15	1		*2K-PLASTIC ADHESIVE	Necessary	85.94 FS	*85.94 FS
16	1		*BONDING AGENT FOR PLASTIC	Necessary	68.85 FS	*68.85 FS
17	1		*UNBEKANNT REINFORCEMENT	Not Necessary	674.24 FS	*- FS
18	1		*SPOILER RR BUMPER LOWER SPOILER	Deformed	339.02 FS	*339.02 FS
19	1		*REFLECTOR LH	Not Necessary	48.26 FS	*- FS
20	1		*REFLECTOR RH	Cracked	48.26 FS	*48.26 FS
21	1		*TAILLIGHT LHR OUTER	Not Necessary	881.46 FS	*- FS
22	1		*LED TAIL L LHR INNER	Not Necessary	594.24 FS	*- FS
23	1		*LED TAIL L RHR INNER	Not Necessary	594.24 FS	*- FS
24	1		*REAR TRUNK	Bent	4,644.37 FS	*4,644.37 FS
25	1		*HOOD LOCK	Not Necessary	173.67 FS	*- FS
26	1		*COVER - LO BOOT LID LOCK COVER	Not Necessary	10.82 FS	*- FS
27	2		*RIVETTED CAP NUT	Not Necessary	5.28 FS	*- FS
28	1		*REAR WINDO REAR WINDSCREEN	Necessary	1,001.16 FS	*1,001.16 FS
29	1		*INSCRIPTIO SKODA WORDING	Necessary	91.09 FS	*91.09 FS
30	1		*INSCRIPTIO SUPERB WORDING	Necessary	112.91 FS	*112.91 FS
31	1		*SKODA EMBL	Necessary	63.90 FS	*63.90 FS
32	2		*1K WINDOW ADHESIVE	Necessary	102.88 FS	*102.88 FS
33	1		*ALL PURPOSE CLEANER	Necessary	102.88 FS	*102.88 FS
34	1		*PRIMER	Necessary	30.27 FS	*30.27 FS
35	2		*APPLICATOR	Necessary	22.32 FS	*22.32 FS
36	1		*ACTIVATOR	Necessary	26.27 FS	*26.27 FS
37	1		*STRIP 3RD BRAKELIGHT STRIP	Necessary	30.26 FS	*30.26 FS
38	1		*SENNSOR LIN OPENING TAILGATE SENSOR LINE	Not Necessary	178.06 FS	*- FS
39	1		*CONTROL UNIT FOR HOOD REA OPENING TAILGATE CONTROL UNIT	Not Necessary	384.92 FS	*- FS
40	1		*REAR PANEL END PANEL INNER	Not Necessary	848.22 FS	*- FS
41	1		*END PLATE END PANEL OUTER	Bent	139.40 FS	*139.40 FS
42	1		*ZINC SPRAY	Necessary	72.86 FS	*72.86 FS
43	1		*2K-BODY ADHESIVE	Necessary	469.52 FS	*469.52 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SEALANT CAB BE SPRAYED	Necessary	66.78 FS	*66.78 FS
45	1		*BOLT FOR SPARE WHEEL MOUN	Not Necessary	24.34 FS	*- FS
46	1		*ALU-LAMIN, INSULATION FLOOR PAN INSULATION	Not Necessary	43.65 FS	*- FS
47	1		*LONG=LIFE UNDERSEAL REAR NUMBER PLATE	Not Necessary	92.69 FS	*- FS
48	1		*SOLAR FILM	Necessary	400.00 FS	*400.00 FS
49	1		*DECKLID WEATHERSTRIP	Necessary	158.46 FS	*158.46 FS
50	2		*GAS-FILLED	Necessary	402.82 FS	*402.82 FS
51	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
52	1		*TAILLIGHT RHR OUTER	Not Necessary	881.46 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) 17,513.73 11,379.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,040.00	3,360.00
4	SPRAY PAINTING	New	3,200.00	2,400.00
5	LABOUR TO REPLACE REAR WINDSCREEN	New	840.00	840.00
6	REAR WATER LEAK TEST	New	150.00	150.00
7	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
8	R&R REAR LUGGAGE TRIM	New	840.00	420.00
9	R&R ROOFLINING TO R&R BOOT LID HINGE	New	1,260.00	1,260.00
10	LABOUR TO REPAIR FLOOR-PAN	New	840.00	840.00
11	SPRAY PAINT FLOOR-PAN	New	800.00	800.00
			Gross Labour Cost (\$)	11,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >