

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22005218/KQY3N2**Date:** 07/06/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000836		
<b>Claimant Vehicle No :</b>	SHD267G	<b>Insured Vehicle No :</b>	SLC1804H		
Date of Loss:	31/05/2022	Nature of Claim:	TP	Claim No:	M2202767

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD267G</b>	Engine No:	M9R8839C002921
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC282311
Reg. Date:	20/11/2015 (Man. Year: 2015)	Odometer:	838191 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,611.14	7,415.29	5,195.85	41.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	2,530.00	3,050.00	54.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,191.14</b>	<b>9,945.29</b>	<b>8,245.85</b>	<b>45.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>(S\$)</b>	18,191.14	6,000.00	12,191.14	67.02
<b>+ GST 7.00/7.00% (S\$)</b>	1,273.38	420.00	853.38	67.02
<b>Nett Amount (S\$)</b>	<b>19,464.52</b>	<b>6,420.00</b>	<b>13,044.52</b>	<b>67.02</b>

INSPECTION

Date of Assignment:	01/06/2022		
Date Inspected:	01/06/2022	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	8.0 days		

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 07 Jun 2022)

**Parts:** 143    RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHD267G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Distorted	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	98.10 FL	-	*98.10 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	-	*80.80 FL
7	1		*BUMPER RETAINER LH REAR	Distorted	54.20 FL	-	*54.20 FL
8	1		*ABSORBER REAR	No such part	217.30 FL	-	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
10	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	-	*114.50 FL
11	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	-	*- FL
12	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	-	*745.80 FL
13	1		*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	-	*404.56 FL
14	1		*SPARE WHEEL PANEL	Repair	1,229.40 FL	-	*- FL
15	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	-	*- FL
16	1		*TAILLAMP LH	Cracked	401.40 FL	-	*401.40 FL
17	1		*TAILLAMP RH	Serviceable	401.40 FL	-	*- FL
18	1		*BOOT REAR	Bent	1,677.20 FL	-	*1,677.20 FL
19	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
20	1		*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
21	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	-	*277.70 FL
22	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	-	*- FL
23	1		*BUMPER REFLECTOR LH	Broken	16.60 FL	-	*16.60 FL
24	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	-	*- FL
25	1		*BOOT HINGE LH	Repair	254.20 FL	-	*- FL
26	1		*BOOT HINGE RH	Repair	254.20 FL	-	*- FL
27	1		*BOOT STRUT LH	Serviceable	145.10 FL	-	*- FL
28	1		*BOOT STRUT RH	Serviceable	145.10 FL	-	*- FL
29	1		*BOOT LOCK	Repair	246.60 FL	-	*- FL
30	1		*BOOT LOCK CATCH	Repair	41.70 FL	-	*- FL
31	1		*BOOT FINISHER	Serviceable	344.70 FL	-	*- FL
32	1		*FENDER PANEL REAR LH	Buckled	1,933.20 FL	-	*1,933.20 FL
33	1		*WHEELARCH REAR LH	Serviceable	275.40 FL	-	*- FL
34	1		*SET PARKING AID	Shorted	700.00 FS	-	*400.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*66.00 FS
36	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*- FS
37	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*- FS
38	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*- FS
39	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*- FS
40	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	-	*66.00 FS
41	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	-	*- FS
42	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
43	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
44	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	-	*40.00 FS
45	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS
46	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	-	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.							
Sub Total (\$)					13,840.18	8,165.66	
- List Item Discount on L Items 10.00/10.00% (\$)					1,229.04	750.37	
Total Parts (\$)					12,611.14		7,415.29

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	880.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,000.00	1,200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,580.00</b>	<b>2,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >