

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 5392H

| Qty | Description of Parts  | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS  |                         |                               |                   |
| 1   | LID   | BENT                    | 961.30                        | 832.00            |
| 1   | LID-JAZZ EMBLEM   | NECESSARY               | 62.10                         | 62.10             |
| 1   | LID LOCK  | DENTED                  | 94.80                         | 94.80             |
| 1   | LID CHROME MLDG   | SERVICEABLE             | 199.60                        | -                 |
| 1   | REAR BUMPER   | BENT                    | 492.60                        | 492.60            |
| 2   | REAR BUMPER RETAINER  | DISTORTED               | 97.00                         | 97.00             |
| 2   | REAR BUMPER COVER   | SERVICEABLE             | 56.40                         | -                 |
| 1   | REAR END PANEL  | TO REPAIR SEE<br>LABOUR | 434.30                        | -                 |
| 1   | END PANEL TOP GARNISH   | SERVICEABLE             | 144.60                        | -                 |
| 2   | TAILLAMP  | CUT / CRACKED           | 1,665.60                      | 1,081.00          |
| 1   | SPARE TYRE PANEL  | TO REPAIR SEE<br>LABOUR | 692.30                        | -                 |
| 1   | TAILGATE DOOR BOARD   | SERVICEABLE             | 197.90                        | -                 |
|     | LESS 20% DISCOUNT   |                         | -1,019.70                     | -531.90           |
|     |   |                         | 4,078.80                      | 2,127.60          |
|     | SPECIAL NETT ITEMS  |                         |                               |                   |
| 4   | REVERSE SENSOR (SN)   | SHORTED                 | 440.00                        | 200.00            |
|     |   |                         | 440.00                        | 200.00            |
|     | <u>LABOUR</u>   |                         |                               |                   |
|     | REMOVE / REINSTALL REAR WINDSCREEN GLASS.   |                         | 180.00                        | 120.00            |
|     | REMOVE INNER GARNISH, REAR SPEAKER HOOD, REAR INTERIOR CUSHION SEAT, ROOF LINING ENABLES JOB CARRY OUT REINSTALL AFTER JOB DONE.  |                         | 250.00                        | 60.00             |
|     | TO REMOVE DAMAGED PARTS N ATTACHMENT CUT N WELD DAMAGED PANELS. TO STRAIGHTEN REAR CHASSIS WHERE NECESSARY. REPAIR / RESHAPE DAMAGED AREAS. REPLACE / REALIGN ALL PARTS INTO SAME POSITION. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND SPARE TYRE PANEL. |                         | 1,100.00                      | 600.00            |

Report Ref No. CS/UOI22005221/Kty3e2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------|-----------|-------------------------------|-------------------|
|     | TO SPRAY PAINT.      |           | 900.00                        | 600.00            |
|     |                      |           | 2,430.00                      | 1,380.00          |
|     | GRAND TOTAL          |           | 6,948.80                      | 3,707.60          |

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) 2,950.00

Report Ref No. CS/UOI22005221/Kty3e2

KONG SENG CHEONG

**Licensed Appraiser**